



LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

**SURVEY &
REMONUMENTATION**

FEB 1 4 2006

SECTION

For corners in _____
Lake _____
(County) _____ Located in: _____ Corner Code # _____

- Public Land Survey _____
T 18 N R 14 W D-7
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
- Property Controlling _____
in Section _____ S _____
- Miscellaneous _____
Property in Sec. _____ S _____

Register of Deeds Stamp & File Number

- Lot No. _____ Recorded Plat _____
- Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						

I, Patrick N. Johnson, in a field survey on October 10, 2005, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

D-7: Quarter corner common to Section 17 & 20, Sweetwater Township, Lake County, Michigan.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

- 1838 S. Sibley, G.L.O.
Set post
#1 8" White Oak N70°W 13 links (8.6')
#2 10" Pine S59°E 10 links (6.6')
- 1931 G. Johnson
Shows corner equidistant between Section corners, with a distance of 2574.5' each way. No monument stated.
#3 10" Yellow Pine S67°-30'E 17.5'
- 1964 R. Griffin, LS 13584
L.C.R.C. Liber 01, Page 100
Found 1-1/4" x 12" railroad coupling pin.
#3 13" Red Pine S67°-30'E 17.85'
#5 7" White Oak S43°W 31.40'
#6 Red Pine (no size) N06°W 32.60'
#7 6" Post West 1.70'

- 1940 H. Arnouts (U.S.F.S. employee)
Found steel stake
#3 12" Red Pine S67°E 26 links (17.2')
#4 Location poster South 1 link

- 1998 G. Bonney, LS 12016
Survey recorded Liber 004, Page 0264
Measured 2567.36 West to Section Corner.
Found U.S.F.S. monument, no witnesses given.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a 5" square concrete monument with brass cap, projecting 18" above ground. There is no occupation evident at the corner location. The corner fits well with all recovered accessories.


Condition of accessories: #1 Did not locate, #2 Did not locate, #3 Found in good condition, #4 Gone, #5 Found in good condition, #6 Found in good condition, #7 Gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I accepted the 5" x 60" square concrete monument with brass cap as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

- | | | | |
|--------------------------|-------|--------|----------------------------------|
| #3 14" Red Pine | S64°E | 17.80' | Found dock spike in North face. |
| #6 11" Red Pine | N02°W | 32.60' | Set 60d spike in West face. |
| #5 11" White Oak | S48°W | 31.40' | Set 60d spike in Southeast face. |
| 10' & 16" Twin White Oak | N37°E | 54.60' | Set 60d spike in East face. |

Signed by Date 12-19-05
Patrick N. Johnson



Surveyor's Michigan License No. 47956 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Approved by Peer Review Group on 12-12-05
Robert L. Weitherell, County Representative. R. L. W.