LAND CORNER RECORDATION CERTIFICATE

Filling Requirement of Act 74, Mich., P.A. 1970

For corners in Lake (County)

Located in:

Corner Code# SURVEY & REMONUMENTATION

JAN 16 2004

SECTION

Register of

RECORDED
LAKE COUNTY, MI
21 OCT 2003 1:02:01 PM
SHELLY MYERS
REGISTER OF DEEDS

Liber 5 Page 237

1. Public Land Survey — T18N R14W — G-9
2. Property Controlling in Section — S___ T__N R__W
3. Miscellaneous Property in Sec. — S___ T__N R__W

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____



I, Robert L. Wetherell, in a field survey on July 18, 2003, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

G-9 Section corner common to Sections 21-22 – 27 & 28

A. Description of original monument and accessories and/or subsequent restoration:

1838 S. Sibley, G.L.O.
#1. 12" Pine N4°E, 70 Lks.
#2. 10" Pine S14°W, 35 Lks.

Undated G. Johnson, Co. Surveyor
#3. 9" J. Pine S77°E, 21 Lks.
#4. 8" J. Pine South, 47 Lks.

1908 G. West, Co. Surveyor
"Found stumps of original Brg. Trees"
#5. 18" W. Pine stump N58°30' E, 98 Lks.
#6. 7" B. Oak S53°45'E, 91 Lks.

1930 G. Johnson, Co. Surveyor
#7. 10" Black Oak S46°30'E, 72'
#8. 6" J. Pine N30°15'W, 27.5'

1949 G. Blass, L.S. 5489
¾" Pipe & wood stake
#9. 8" W. Oak S50°W 58.3'
#10. 12" J. Pine S3°W 33.0'

1957 G. Blass, L.S. 5489
#9. 8" W. Oak S50°W 58.3'
#11. 5" B. Oak N35°E 23.71'
#12. 3" R. Pine S85°W 4.05'

1964 R. Griffin, L.S. 13584
L.C.R.C., L.01, Pg. 115
Found ¾" pipe & West's accessories
Set monument
#11. 6" B. Oak N33°E 24.00'
#13. 7" W. Oak S40°E 87.40'
#9. 10" W. Oak S43°W 68.17'
#14. 5" R. Pine N71°W 28.90'
Post N. 1.5'

1988 S. Barnett, L.S. 16923
Survey Record, L.03, Pg. 148
Distance West = 2495.86'
Distance North = 2665.88'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found Griffin's 5" square concrete monument 20' North of the center of an E-W two track road. It checks well with all the recovered accessories.

Condition of Accessories: #1 through #6, Gone, #7, Found clump at 72' , #8, Gone, #9, Found at 68', #10, Found in good condition, #11 through #14, Found in good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I accepted the 5" concrete monument as a substantial marker for the corner and is accepted as a careful and faithful perpetuation of the position of the original corner.

12" W. Oak	S36°E	87.53'	(60 d. spike in SW side) #13
12" W. Oak	S48°W	68.18'	(Dock spike in NW side) #9
12" R. Pine	N68°W	28.94'	(Dock spike in S. side) #14
9" R. Pine	N24°E	20.24'	(60 d. spike in E. side)

STATE OF MICHIGAN
ROBERT L. WETHERELL
PROFESSIONAL SURVEYOR
No. 24624
LICENSED PROFESSIONAL SURVEYOR

Signed by Robert L. Wetherell
Surveyor's Michigan License No. 24624

Date OCT 3, 2003

RATIFIED BY THE LAKE CO. PEER REVIEW GROUP IN ACCORDANCE WITH P.A. 345
CHAIRMAN PLW DATE: 10/02/03

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING JANUARY, 1999