

2013 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Presque Isle Located In: _____ Corner Code # _____
(county)

Instrument
201300004603 OR Liber Page
544 893

1. Public Land Survey
T 33N R 5E E-11
T _____ R _____
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling in Section
S _____ R _____
S _____ R _____
3. Miscellaneous Property in Sec.
S _____ R _____
S _____ R _____

201300004603
Filed for Record in
PRESQUE ISLE COUNTY
CATHY I. IDALSKI, REGISTER OF DEEDS
12-10-2013 AT 03:49 PM.
LC-REMON 17.00

OR Liber 544 Page 893 - 894
Register of Deeds Stamp & Figure Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, **Travis L. Horrocks**, in a field survey on March 27, 2013 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-11
SEEBACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11
FD. REMNANTS OF WOOD STAKES IN MUCK
20' SOUTH OF E-W SMOOTH WIRE FENCE
N 30° W 25.30' STUMP MOUND
N 10° W 19.90' STUMP MOUND
S 50° E 45.80' LARE BROKEN & CHARRED W. PINE STUMP
CORNER FITS RECORDED SURVEY OF LARRY BEAUREGARD
LIBER 205, PAGE 219-221

C. Description of monument for corner and accessories established to perpetuate the position of the corner:

E-11
1/2" ROD & REMON CAP #59298
20' SOUTH OF E-W SMOOTH WIRE FENCE
N 40° W 14.40' 4" MAPLE #59298
N 50° W 21.36' 5" MAPLE #59298
S 30° W 13.40' 4" MAPLE #59298
S 30° E 20.85' 4" MAPLE #59298

attified by Peer Group
in accordance with P.A. 345
Chairman Mark J. Chin
Date 9-19-2013

Signed by [Signature]
Surveyor's Michigan License No. 59298

WITNESS TAGS & NAILS USED
Date 09/23/13

A	B	C	D	E	F	G	H	I	J	K	L	M
1	2	3	4	5	6	7	8	9	10	11	12	13
14	15	16	17	18	19	20	21	22	23	24	25	26
27	28	29	30	31	32	33	34	35	36	37	38	39
40	41	42	43	44	45	46	47	48	49	50	51	52

