

2014 STATE OF MICHIGAN, PRESQUE ISLE COUNTY REMONUMENTATION Received  
 PRESQUE ISLE COUNTY  
 01-09-2015 09:11 am.

LAND CORNER RECORDATION CERTIFICATE  
 Filing Requirement of Act 74, Mich. P.A. 1970 as Amended Instrument  
 201500000104 OR Liber Page  
 558 961

For corners in

<b>Presque Isle County</b> (County)	Located in:	Corner Code #
1. Public Land Survey	T-33N R-5E	F-9
	T R	
	T R	
	T R	
2. Property Controlling in Section	T R	
	T R	
3. Miscellaneous Property in Sec.	T R	
	T R	

201500000104  
 Filed for Record in  
 PRESQUE ISLE COUNTY  
 CATHY I. IDALSKI, REG OF DEEDS  
 01-09-2015 AT 09:21 am.  
 LC-REMON 17.00  
 OR Liber 558 Page 961 - 962

Register of Deeds Stamp & Figure Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
1	2	3	4	5	6	7	8	9	10	11	12	13
14	15	16	17	18	19	20	21	22	23	24	25	26
27	28	29	30	31	32	33	34	35	36	37	38	39
40	41	42	43	44	45	46	47	48	49	50	51	52
53	54	55	56	57	58	59	60	61	62	63	64	65
66	67	68	69	70	71	72	73	74	75	76	77	78
79	80	81	82	83	84	85	86	87	88	89	90	91
92	93	94	95	96	97	98	99	100	101	102	103	104
105	106	107	108	109	110	111	112	113	114	115	116	117
118	119	120	121	122	123	124	125	126	127	128	129	130
131	132	133	134	135	136	137	138	139	140	141	142	143
144	145	146	147	148	149	150	151	152	153	154	155	156

I, **Travis L. Horrocks**, in a field survey on June 10, 2014, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

**RECEIVED**  
 FEB 25 2015  
 Office of Land Survey &  
 Remonumentation

F-9  
 SEE BACK



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-9  
 FOUND 1/2" ROD 18" NORTH OF E-W TRAIL ROAD  
 N 43° W 26.60' 7" ASH #21559  
 S 64° W 13.95' 4" DEAD ASH #21559  
 S 75° E 24.96' 24" DEAD TWIN ASH #21559  
 N 38° E 12.18' STUMP MOUND  
 N 20° E 7.81' 4" ASPEN #21559  
 S 89° W 91.12' ROTTED OFF FE COR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-9  
 1/2" ROD & REMON CAP #59298  
 18" NORTH OF E-W TRAIL ROAD  
 N 43° W 26.60' 7" ASH #21559 (OW)  
 N 45° W 12.88' 3" MAPLE #59298  
 S 64° W 13.95' 4" DEAD ASH #21559 (OW)  
 S 30° W 32.30' 3" MAPLE #59298  
 S 75° E 24.96' 24" DEAD TWIN ASH #21559 (OW)  
 N 20° E 7.81' 4" ASPEN #21559 (OW)

Fulfilled by Peer Group  
 in accordance with P.A. 346  
 Chairman *Alvin J. Plo*  
 Date 11-4-2014

Signed by *Travis L. Horrocks*  
 Surveyor's Michigan License No. 59298

WITNESS TAGS & NAILS USED

Date 11/04/14

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975  
 Revised Jan., 1983  
 Revised Oct., 1995