

State of Michigan Remonumentation Program  
For Presque Isle County

PRESQUE ISLE COUNTY  
RECORDED

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

PRESQUE ISLE Located In: Corner Code #  
(County)

*John M. Samb*  
REGISTER OF DEEDS

- Public Land Survey  
T 36N R 2E K-12  
T R  
T R  
T R
- Property Controlling in Section  
S T R  
S T R  
S T R  
S T R

LIBER **310** PAGE **945**

Register of Deeds Stamp & File Number

- Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6	5	4	3	2							
3													
4		7	8	9	10	11	12						
5													
6		13	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11													
12		31	32	33	34	35	36						
13													

I, Ronald Bischer, in a field survey on May 5, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1856 Resurvey - GLO Notes  
Set Wood Post  
W. Birch N60°W 14 links  
Aspen 10" S55°E 8 links  
10-19-79 - Ronald R. Bischer  
Set ½" Rod by Single proportion  
S32°W 38.51', 6" Birch  
S25°E 51.92', 8" Norway  
N46°W 22.15', 6" Oak


10-30-79 - Ronald R. Bischer  
½" Rod  
N46°W 22.15', 6" Oak  
S25°E 51.92', 8" Norway  
S32°W 38.51', 6" Birch

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" Rod and Cap #15410  
N46°W 22.15', 8" Oak  
S25°E 51.92', 8" Norway  
stump remains intact  
S32°W 38.51', 8" Birch

**SURVEY &  
REMONUMENTATION**

SEP 09 1994  
COMMISSION



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

½" Rod and Cap #15410  
N46°W 22.15', 8" Oak  
S32°W 38.51', 8" Birch  
S23°E 45.69', 8" Birch  
S70°W 12.68', 3" Maple

Ratified by Peer Group  
in accordance with P.A. 345  
Chairman *Delmar E. Porter*  
Date July 29, 1994

Witness tags and nails used.

Signed by Ronald R. Bischer

Date July 20, 1974

Surveyor's Michigan License No. 22428