

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF-: LOCATED IN-: CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 33 N. R. 3 W. G-5, G-6, G-7, H-5, H-6, H-7 I-6
2. PROPERTY CONTROLLING IN SECTION T. N. S. R. E. W.
3. MISCELLANEOUS PROPERTY IN SECTION T. N. S. R. E. W.
4. LOT NO. RECORDED PLAT
5. PRIVATE CLAIMS

State of Michigan
County of Cheboygan
Received for Record
SEP 20 1977 At 3:45 PM AM
Jean Simonson
Register of Deeds
REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Orlando Doyle, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April, 1974, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Table with 4 columns: Monument Description, Bearing, Distance, and Notes. Includes entries for G-5 Set 3/4" Pipe (10" Pine, 3" Oak, 12" Pine), G-6 Set 3/4" Pipe (12" Spruce, 5" Spruce, 6" Spruce), and I-6 Found 1 1/4" Pipe (P. P. South, 6" Tw.Oak, 3" Elm).

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Table with 3 columns: Monument Description, Bearing, Distance. Includes entries for G-7 Found 1" Pipe/plate (8" Ash, 6" Maple, 10" Ash) and H-5 Set 1" Pipe (5" Tamarack, 4" Spruce, 6" Tamarack).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Table with 3 columns: Monument Description, Bearing, Distance. Includes entries for H-6 Set 1" Pipe/ W. Plug (8" G. Birch, 10" Tw.G. Birch, Fence Post) and H-7 Set 1" Pipe (10" Cedar, 10" Cedar, 5" Spruce).



SIGNED BY Orlando Doyle DATE Sept. 21, 1977
SURVEYOR'S MICHIGAN REGISTRATION NO. 7319 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY CHIEF OF SURVEY PARTY DATE
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR DATE (SEAL)

LIBER 001 PAGE 225

SURVEYOR'S MICHIGAN REGISTRATION NO.