

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended SECTION

For corners in

RECEIVED FOR RECORD
MARY ELLEN TRYBAN, CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN
09/21/2006 11:28:40 AM



Located In: _____ Corner Code # _____

CHEBOYGAN
(County)

RECEIPT# 10763, STATION 2
\$14.00 LAND CORNER RECORDAT

1. Public Land Survey T 35N R 2W E-11

T ___ R ___
T ___ R ___
T ___ R ___
T ___ R ___
T ___ R ___
T ___ R ___
T ___ R ___

2. Property Controlling S ___
in Section S ___
3. Miscellaneous S ___
Property in Sec. S ___

Register of Deeds Stamp & File
Number

4. Lot No. _____, Recorded Plat
5. Private Claims

I, BRIAN K. FULLFORD, in a field survey on July 18, 2006 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6	5	4	3	2	1						
3													
4		7	8	9	10	11	12						
5													
6		18	17	16	15	14	13						
7													
8		19	20	21	22	23	24						
9													
10		30	29	28	27	26	25						
11		31	32	33	34	35	36						
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

- December 1960
LCRC, Liber A, Pg 381
Set 1" pipe w/ 4" brass cap
7" J. Pine N37½°W 49 links
10" Y. Pine N38°W 65½ links
5" B. Oak S83°W 68½ links
- January 1962
LCRC, Liber A, Pg 381
Dean C. DeLaMeter #5778
1" pipe w/ 4" brass cap
7" J. Pine N37½°E 49 links
10" J. Pine N38°W 65½ links
5" B. Oak S83°W 68½ links
- August 1855 Harvey Mellen
Set post
10" Y. Pine S86°E 19 links
10" Y. Pine N84°W 52 links
- 1960 Unrecorded DNR survey
Plan No. R-16-G
Kenneth Ostling #10068
DNR survey shows cor.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- Fnd. MDNR Monument
11" J. Pine South 10.07'
8" J. Pine N22°E 14.75'
13" Red Oak S89°W 45.06'
8" J. Pine N84°W 49.70'
Stump N71°E 2.90'
Stump S64°W 20.29'
14" Stump N31°W 43.02' Scribed BT
- Set tag#41099
Set tag#41099
Set tag#41099
Set tag#41099

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- E-11 MDNR Monument. Position is accepted as a careful and faithful perpetuation of the original corner.
- 11" J. Pine South 10.07'
8" J. Pine N22°E 14.75'
13" Red Oak S89°W 45.06'
8" J. Pine N84°W 49.70'
- Set tag#41099
Set tag#41099
Set tag#41099
Set tag#41099


Signed by Brian K. Fullford
Surveyor's Michigan License No. 41099

July 1967 MDOT project #16022
MDOT William R. Downey
Fnd. 4" brass cap on 1" pipe
7" J. Pine N38°E 32.34'
10" J. Pine N38°W 43.23'
5" Bl. Oak S83°W 45.21'

March 1999 Survey, Liber 721, Pg 194
Brian K. Fullford #41099
Fnd. 1" pipe w/ 4" brass cap
8" J. Pine N18°E 14.52'
4" J. Pine S88°E 2.95'
12" J. Pine S65°W 20.21'
10" J. Pine S01°E 10.20'

ACCEPTED BY THE CHEBOYGAN
COUNTY SURVEY PEER GROUP
AS THE OFFICIAL CORNER UNDER
P.A. 245 OF 1990, AS AMENDED, AT
A MEETING HELD ON 8-24-06

Brian K. Fullford



Date September 11, 2006