Land Corner Recordation Certificate Attachment B to 2020 Annual Grant Agreement

Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2020 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2018 State Survey and Remonumentation Grant Agreement.

Notes:

- *No more than two Original Public Land Survey Corners can be recorded on this certificate
- *If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the Corner may be identified on this certificate.
- *If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county.

For corner(s) in:

Emmet County, Michigan

Springvale Township

881 Emmet County Remon Program (ECRP) Corner No.` Corner Code **Survey Township Corner Type**

Original Public Land	T 34 N	R_04 W_	I-13
*MCL 54.202(g) *MCL 54.262(g) 3443		R R	

*MCL 54.202(i) *MCL 54.262(h)

10 30 26 36

Protracted Public Land Survey Corner

*MCL 54.202(k)

*MCL 54.262(i)

Part A: Corner History--Abstract....See back of this page for chronological history

*In 1840 the GLO Sets a Post and Takes Witness's.

*In 1892 County Surveyor Robinson found the GLO Post and Set a Limetone

*In the 1920's Schaaf Set a 1" Pipe based on the Found Closing Corner to the West in the Intersecition of Roads East/West/North. This Position has been used by surveyors since.



OFFICIAL SEAL Received for Record: DOC # 5181473 L: B P: 734 Doc Type: LCR 12/30/2020 09:40:53 AM Karen Cosens, Register of Deeds Emmet County, MI, Page 1 of 4

Attachment B to 2020 Annual Grant Agreement

Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2020 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2018 State Survey and Remonumentation Grant Agreement.

Notes:

- *No more than two Original Public Land Survey Corners can be recorded on this certificate
- *If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the Corner may be identified on this certificate.
- *If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county.

For corner(s) in:	Emmet County, Michigan			Springvale Township		
Emmet County Remon Program (ECRP) Corner No.` Corner Type Survey Township		881 Corner Code	er			
Original Public Land		T 34 N	R <u>04 W</u>	I-13		
Survey Corner *MCL 54.202(g)		TT	R		A B C D E F G H I J K L P	1
*MCL 54.262(g)		Т	R		2 _ 6 5 . 4 . 3 . 2 1	
					4. 78 . 9 . 10 . 11 12	•
Property Controlling					5	
*MCL 54.202(i)	s	_ T	R		6. 18 17 16 - 15 14 13	:
*MCL 54.262(h)	s	_ T	R		8 20	
					10 30 -29 28 27 26 25	
Protracted Public Land S	urvey				11	٠
Corner		т	R	4-	12 31 32 33 34 35 36	
*MCL 54.202(k)		Τ	R			
*MCL 54.262(i)		Т	R			
		T	R			

Part A: Corner History--Abstract....See back of this page for chronological history

^{*}In 1840 the GLO Sets a Post and Takes Witness's.

^{*}In 1892 County Surveyor Robinson found the GLO Post and Set a Limetone

^{*}In the 1920's Schaaf Set a 1" Pipe based on the Found Closing Corner to the West in the Intersection of Roads East/West/North. This Position has been used by surveyors since.

Emmet County Remonumentation Program

Emmet County Remon Program Corner No. 881

Springvale Township, Emmet County T34N R04W Corner Code No. H-13 Corner Common to Section 34/35 T34N-R04W

<u>Date</u>	<u>Surveyor</u>		Found / S	<u>et</u>		
1840	GLO		Set Post			
		1	N33E	32 Links	12" Sugar	21.1 Feet
		2	N53W	5 Links	8" Sugar	3.3 Feet
1892	Robinson		Found Post, Set 6.5" Gray Lime Stone			
		3	N48.30E	66.5 Links	20" Sugar	43.9 Feet
		4	N45W	44 Links	18" Sugar	29.0 Feet
1920'S	Schaaf		Set 1" Pipe	based on Fo	und Closing Corner	
1960	Ostling		Found 1" Pipe			
		5	N35E	59.8	7" Red Pine	
		6	N20W	72.3	5" Elm	
1960's	Rd. Comm.		Found 3/4" Pipe			
		7	NE	69.7	8" Pine	
		8	SE	47.30	12" Elm	
		9	SW	45.10	16" Elm	
		10	NW	72.40	6" Elm	

Land Corner Recordation Certificate Attachment B to 2020 Annual Grant Agreement T<u>34 N</u> __ R<u>04 W</u>I-13

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

Found the Original Government Wood Post Below a Vertical Limestone with Sharp Top, below Schaff's Pipe in Concrete.

5) N38E

59.24

24" Red Pine, Found Mostly Overgrown 40D Nail in Southeast Face, Set nail/cap 56482

over found overgrown nail

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

The Found Pipe in Concrete was replaced with a 2" Aluminum Pipe 3' long withBase Magnet and Standard Emmet County Remon Cap stamped PS No. 56482. This position is accepted as the position of the original corner.

5) N38E	59.24	24" Red Pine, Set Nail/Cap PS No. 56482 over Found Mostly Overgrown 40D Nail in Southeast Face
S47E	83.27	6" Red Pine, Set Nail/Cap PS No. 56482 In Northeast Face
S08E	101.58	6" Red Pine, Set Nail/Cap PS No. 56482 In East Face
S89W	190.61	20" Twin Maple, Set nail/tag PS No. 56482 in South Face
N19W	64.74	36" Rock, Found Chisled X in Top Drilled Hole in Center of Found "x". Set 2-1/2" Mag Nail in Drill Hole

Date of		Datum and				
<u>Observation</u>	<u>Latitude</u>	<u>Longitude</u>	Adjustment Year	Epoch Date		
1-Dec-20	45° 17' 23.66"	84° 46' 24.00"	NAD 1983 (2011)	2010.0000		

Method for coordinate determination:

Coordinate determination based on RTK Observation processed utilizing single vector to base station. Base Station was processed utilizing a OPUS Static Solution.

<u>Disclaimer on accuracy of values reported relative to their use:</u>

This position should not be utilized for survey purposes. This is intended to represent a position to the nearest foot of relative position.

I, Neil A. Holshoe, in a field survey on 11 November 2020, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Date 03 Dec 2020

OFESSION

Date 11 Dec 2020

Professional Surveyor's License No:

#56482

Benchmark Engineering Inc., 607 E. Lake Street, Harbor Springs, MI., 49740

I Richard E. Oelke, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on 10 December 2020 and is accepted for filing in the Emmet County Remonumentation Program.

Richard E. Oelke

APPROVED LAND CORNER P.A. 345 CF 1990 Emmet County

No

Professional Surveyor's License No:

#33983