CONS. 4047 4/56

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 34 NR 4 W ...

						Emme	t 	COUN	1TY
DESCRIPTION	0	F CORNER	Section	on corn	er co	mmon to	Section	ns 26-27-34-	35
DESCRIPTION	OF	CORNER	MONU	MENT1"	pipe	with 4	" brass	cap	
WITNESSES	ТО	CORNER							
			22"	Elm		NOTE	-	35½ Links	-
			611	Maple	-	86TM	-	43½ Links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a survey in this township. Could find no evidence of a previous corner. Set corner on straight line over 1/4 and section corner north, at proportionate measurement between 1/4 corner north and section corner south. This point falls near center of N-S county road, and conforms very nearly to old field edge west. Did not consider double proportion since great distance between corners and extremely hilly terrain would make this method quite unreliable. It seem quite possible the road could have been constructed to a previous corner, evidence of which has been destroyed.

Corner was placed and witnessed July 27, 1960.

SURVEYORS SEAL

SIGNED leuneth & Octling
REGISTERED LAND SURVEYOR

DATE 8/1/60.