Cons. 4047

45

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_34_ NR_4_T__

	-				-	Emme	t	COUN	۲Y
DESCRIPTION	OF	CORNER	Section	on cor	ner o	ommon to	Sect	lons 26-27-34-3	5
DESCRIPTION	OF	CORNER	MONUI	MENT	" pip	e with 4	" bra	as_cap	
WITNESSES .	то	CORNER							
			22#	Elm		N6TE	-	35½ links	
			6#	Маріе		8 61 M		43½ links	
					-				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew white making a survey in this township. Could find no ewidence of a previous corner. Set corner on straight line over 1/4 and section corner north, at proportionate measurement between 1/4 corner north and section corner south. This point fails near center of N-S county road, and conforms very nearly to old field edge west. Did not consider double proportion since great distance between corners and extremely hilly terrain would make this method quite unreliable. It seem quite possible the road could have been constructed to a previous corner, evidence of which has been destroyed.

Corner was placed and witnessed July 27, 1960.

SURVEYORS SEAL

SIGNED MEGISTERED LAND SURVEYOR DATE 8/1/60.