Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 39 N.R. 3 W Cheboygan COUNTY DESCRIPTION OF CORNER Closing Corner common to Sections 27-34 on SE boundary of Private Claim #334 CORNER MONUMENT I" pipe with 4" brass cap DATE MONUMENT PLACED AND WITNESSED _____ 6/30/61 WITNESSES TO CORNER..... 14.2 ft 12" Spruce N53W N86E 28.2 ft 7" Spruce Sec 27 AND CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while making a survey in this area. Set corner at record measurement NE from closing corner between Sections 33-34, on calculated SE boundary of Private claim. Unable to identify US BTs. This position would make the mile between 27-34 somewhat short of record, but would conform acceptably for bearing.

SURVEYOR'S SEAL

SIGNED County Delling
REGISTERED LAND SURVEYOR

_ DATE 7/5/61

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by Forestry Division survey crew while making a survey in this area. Set corner from probable SE gov't BT stump- the only W. Pine stump in the immediate vicinity. This point checks very good for bearing and distance to section corner on south boundary of township. Too wet to discover anything by excavation. Could find no evidence of previous corner, although a ½" pipe set to preserve traverse information in a Doyle survey is about 73' NW. Our corner was used to control the SE boundary of private claim, and would make the claim width about 40' short of the width prescribed by the gov't description of the Private Claim.

SURVEYOR'S SEAL

SIGNED Leweth Jolling DATE 7/5/61

REGISTERED LAND SURVEYOR

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	T	38 39	- N.R	3	W. W.		
	10)/	.,	_		Cheboygan	COUNTY
DESCRIPTION OF CORNER <u>Secti</u>	on corner	commo	n to Sec	ctions	33 - 3	34 - 3 - 4	
CORNER MONUMENT Set 1" pip	e with 4"	brass	cap				
DATE MONUMENT PLACED AND WIT	MESSED Apr	il 22.	1964				
WITHESSES TO CORNER							
N							
		6" C	edar	N 7	8 W	10.5'	
	town days	6" C	edar	N 5	5 E	36.01	
AND							

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey of this area. Found 3/4" pipe in place as previously established by unknown surveyor. Old township road grades E-W-S. Remains of two probable BTs in place.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Lewelly Detling
REGISTERED LAND SURVEYOR #10068

DATE June 24, 1964

Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

	т	38 39	_ N.R	3	W.	Cheboygan	COUNTY
				-		Cheboygan	COUNTY
DESCRIPTION OF CORNER Sect	ion corner	common	to Sec	tions	34 -	35 - 2 - 3	
CORNER MONUMENTDrove 1'	pipe belo	w surfa	ace				
DATE MONUMENT PLACED AND WI	THESSED Apr	il 22,	1964				
WITNESSES TO CORNER							
N							
		12" I	Balsam	S 55	E	42.3'	
34							
+ 34		7" 5	Spruce	S 54	W	40.41	
AN	ID						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 1/2" pipe in place in N - S road and in line with old grades E and W. Appears acceptable as proper location for corner.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

SIGNED Junetly Detling
REGISTERED LAND SURVEYOR #10968

DATE June 26, 1964

Markinar

16

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

. •	Comers in			
. 0	heboygan Gailnivi	Located In:	Corner Code :##	MAR 1 O 1988
1.	Public Land Survey	Т <u>39N</u> R 3 W	<u> </u>	Joanne Spray
2.	Property Controlling in Section	T R T R S T R	**************************************	CLERK/REGIST R CHEBOYGAN COUNTY, MICHIGAN
3,		S T R S T R		Register of Deeds Stamp & File Number
	Lot No , R	ecorded Plat		ABCDEFGHIJKL

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1" Axle
 - N 10 W 16" Cedar 29.95'
 - S 05 E 15" W. Birch 32.10
 - N 48 E Pine Stump 31.25'
 - N 55 E 20" Aspen 45.64'

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1" Axle N 8 W 16" Cedar 29.94' S 1 E 15" W. Birch 32.13'

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - 1" Axle
 N 08 W 16" Cedar 29.94'
 S 01 E 15" W. Birch 32.13'
 N 26 E 20" Tr. W. Birch 20.10'
 S 56 E 8" W. Birch 17.73'

URER 001 FAGE 340

Signed by James H Surveyor's Michigan License No. 16041

JAMES H.
GRANGER

LAND SHRVEYOR

NO.

16041

LAND SURVEYOR

NO.

16041

LAND SURVEYOR

LAND SURV

March 9, 1988

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

State of Michigan

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	County of Cheboygan
FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER Received for Record
1. PUBLIC LAND SURVEY	3 1-11, J-11, AN
2. PROPERTY CONTROLL ING IN SECTION—, T N. R	FEB 23 1983At 10.30 PN
3. MISCELLANEOUS PROPERTY IN SECTION, T, T, T, T, T	Lean, Simoneon
4. LOT NO, RECORDED PLAT	Pagister of Deeds
5. PRIVATE CLAIMS	
	REGISTER OF DEEDS STAMP AND FILING NUMBER
and rules therefore as required in the current manual of Bureau of Land Management or by a decree of a court and 5 above were, in a field survey on	e, in a field survey on, 19, established or restored as expressed below and in conformance with regulations of survey instructions of the United States Department of the Interior of law. Furthermore, that the corner points mentioned in lines 3, 4, 19, found, recovered, restored, established or re-established of the Michigan State Board of Registration for Land Surveyors or, by a
A. Description of original monument and accessories at	nd/or subsequent restoration:
I-11 Doyle Fd. 1" Axle (1947) N12°W 29.30 10"Cedar	P-11 $1\frac{1}{2}$ " Iron Set by Doyle (1947)
N50°E 45' 10"Aspen S20°E 31.6' 11" W. Birch	
C. Description of monument for corner and accessories of I-11 1" Ax1e N10°W 29.95' 16"Cedar N48°E 31.25' Pine Stur N55°E 45.64' 20" Aspen S05°E 32.10' 15" W. B	n No4 E 37.00' 11" Cedar
SURVEYOR'S MICHIGAN REGISTRATION NO FOR STATE AND UNITED STATES AGENCIES:	DATE October 7, 1982 22428 (BEAL)
SIGNED BYCHIEF OF SURVEY PARTY	DATE.
APPROVED AND SIGNED BYMICHIGAN REGISTERS	DATE
SURVEYOR'S MICHIGAN REGISTRATION NO	DI PAGE GOS