	LAND CORNER RECOR			
	Filing Requirement of	THE CHOMETO		
For Corners In:	Located In Corner Co	20100010001		
Montmorency (County)	Located In Corner Co	201800075064		
1. Public Land Survey	T R	Filed for Record in MONTMORENCY COUNTY, MI		
Property Controlling in Section	S 17 T 32N R 3E 3 S 17 T 32N R 3E 5	TERESA WALKER, REGISTER OF DEEDS 07-11-2018 At 09:01:18 am. LAND CORNER 30.00 Liber 1 Page 826 - 826		
Miscellaneous Property in Section	S 17 T 32N R 3E 5 S T R R			
	S T R	Register of Deeds Stamp & File Number		
4. Lot No:	Recorded Plat:	ABCDEFGHIJKLM		
5. Private Claims: _		2 -6 -5 -4 -3 -2 -1		
I, Carl T. Kiiskila, in a field survey on September, 6, 2016 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				
		12 31 32 33 34 35 36		
A. Description of origina	I monument and accessories and/or subseque			
3 – N 1/16 Corner c	ommon to Sections 17&18 T32N,R03E	5 – CN 1/16 Corner Section 17, T32N,R03E		
This corner was not set during the Original GLO Survey. This corner was not set during the Original GLO Survey.				
B. Description of corner	evidence found and/or method applies in rest	oring or re-establishing corner:		
3 – N 1/16 Corner c	ommon to Sections 17&18 T32N,R03E	5 - CN 1/16 Corner Section 17, T32N,R03E		
Set a 5/8" rerod with 2" Aluminum Cap # 33981 by Standard BLM procedure for subdivision of a section.		Set a 5/8" rerod with 2" Aluminum Cap # 33981 by Standard BLM procedure for subdivision of a section.		
C. Description of monun	nent for corner and accessories established to	perpetuate locating the position of the corner:		
3 - N 1/16 Corner of	common to Sections 17&18 T32N,R03E	5 - CN 1/16 Corner Section 17, T32N,R03E		
5/8" rerod with	2" Aluminum Cap	5/8" rerod with 2" Aluminum Cap		
S01°E 18.9 S82°W 19.3	0' to set N&T on N side 12" Cedar 5' to set N&T on W side 8" Balsam 0' to set N&T on S side 9" Cedar 0' to set N&T on W side 10" Cedar	Witnesses: N30°E 25.95' to set N&T on NW side 6" Balsam N89°E 8.56' to set N&T on N side 24" R. Pine S20°W 31.77' to set N&T on W side 3" R. Pine S74°W 30.95' to set N&T on S side 24" R. Pine		
Set Blue Post 1' North Set		Set Blue Post 1' North		
		STATE OF MICHIGAN		
Signed by:	arl TKushla	Date: 4-18-18 KIISKILA SURVEYOR		
Surveyor's Michigan I	license No : 33981	SURVEYOR &		

Surveyor's Michigan License No.:

33981

LAND CORNER RECORDATION CERTIFICATE

Montmorency		Filing Requirement of	Act 74, Mich. PA 1970
1. Public Land Survey T 32N R 3E C-5 Property Controlling in Section S T R Miscellaneaus Property in Section S T R Loan Kiddle in a felt survey on bord 2.2013 do hereby date that under collections of survey instructions of the United Blass Department of the United Blass of Sections of Se	Montmorency	Located In Corner C	201200075044 1 828
5. Private Claims: 1. Cart T. Kijskilja. In a field survey on June 2, 2016 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the corner manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the Corner corner manual of survey instructions of the United States Department of the Corner corner manual of survey instructions of the United States Department of the Corner corner for the Corner corner for Land Surveyors or by a Decree of a Court of Law, established, received found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 1850 – GLO – Hiram Bumham – Set post for corner of sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for Corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for Corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for Corner of Sections 7,8, 17& 18, T32N,R0	Public Land Survey Property Controlling in Section Miscellaneous	T 32N R 3E C-6 S T R S T R	Filed for Record in MONTHORENCY COUNTY, MI TERESA WALKER, REGISTER OF DEEDS 07-11-2018 At 09:02:03 am. LAND CORNER 30.00 Liber 1 Page 828 - 828
5. Private Claims: 1. Cart T. Kijskilja. In a field survey on June 2, 2016 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the corner manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the current manual of survey instructions of the United States Department of the Corner corner manual of survey instructions of the United States Department of the Corner corner manual of survey instructions of the United States Department of the Corner corner for the Corner corner for Land Surveyors or by a Decree of a Court of Law, established, received found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 1850 – GLO – Hiram Bumham – Set post for corner of sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for Corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for Corner of Sections 7,8, 17& 18, T32N,R03E 1850 – GLO – Hiram Bumham – Set post for Corner of Sections 7,8, 17& 18, T32N,R0	4. Lot No:	Recorded Plat:	
I. Carl T. Kiiskläp, in a field survey on June 2, 2016 do hereby state that under requirements of PA 74, Michigan PA of 1670; the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interfor, Burseu of Land Management of by a decree of a Court of Law and/or that the current points mentioned in lines 1, and 2 above were in conformance with the rules established, monumented in lines 3, 4 and 5 above were in conformance with the rules care points mentioned in lines 3, 4 and 5 above were in conformance with the rules care points mentioned in lines 3, 4 and 5 above were in conformance with the rules care points mentioned in lines 3, 4 and 5 above were in conformance with the rules care points mentioned in lines 3, 4 and 5 above were in conformance with the rules care points mentioned in lines 1, and 2 and 2 above were in conformance with the rules care points mentioned in lines 1, and 2 and 2 above were in conformance with the rules care points mentioned in lines 1, and 2 and 2 above were in conformance with the rules care points mentioned in lines 1, and 2 above were in conformance with the rules care points mentioned in lines 1, and 2 and 2 above were in conformance with the rules care points mentioned in lines 1, and 2 and 2 above were in conformance with the rules care points mentioned in lines 1, and 2 and 2 above were in conformance with the rules care required to the long of the corner of 2 and 3 an	THE RESERVE TO SERVE THE PARTY OF THE PARTY		A B C D E F G H I J K L M
Can't Kisklip, in a field survey on June 2, 2016 do hereby state that under requirements of PA 74, Michigan PA of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey; instructions of the Linder States Department of the tecument manual of survey instructions of the Michigan Beard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: C.5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E Appan 12, S40°E 28 Y. Pine 10 N20°E 30 1986 – L.C.R.C. L.D.O.1, p.399 – Delmer E. Porter P.S.#15410 Found 2" pipe in Concrete (M. Schaah) N20°E 38.28' 16" Spruce N31°E 18.28' 10" Balsam S31°W 33.45' NE Corn. L.D.O.1, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C.5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2" Pipe P.C.R.C. L.D.O.1, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C.5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2" Pipe P.C.R.C. L.D.O.1, p.399. Accepted found gipe as the best available evidence for the position of the original corner. C.5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2" Pipe P.C.R.C. L.D.O.1, p.399. Accepted found Cip as the best available evidence for the position of the original corner. C.5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2" Pipe P.C.R.C. L.D.O.1, p.399. Accepted found Cip as the best available evidence for the position of the original corner. C.5.— Co	5. Private Claims:		2 6 5 4 3 2 1
A. Description of original monument and accessories and/or subsequent restoration: C-5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E 1850 – GLO – Hiram Burnham – Set post for corner to sections 7,8,17 & 18, T32N,R03E 1850 – GLO – Hiram Burnham – Set post for corner to sections 7,8,17 & 18. Aspen 12 S40°E 28 Y. Pine 10 N20°E 30 1986 – L.C.R.C. L.001, p.399 – Delmer E. Porter P.S.#15410 Found 2° pipe in Concrete (M. Schaal) N20°E 38 28° 16° Spruce N64°E 17.19° 8° Maple S31°W 33.45° NE Cor. Cabin B. Description of corner evidence found and/or method applies in restoring or re-establishing corner: C-5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2° Pipe Per L.C.R.C. – L. 001, p.399 – Accepted found pipe as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C.5.— Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2° pipe Vilnesses: N15°E 38.43° to set N&T on E side 28° Spruce S63°E 25.34° to set N&T on N side 1° Balsam S82°W 17.47° to set N&T on Side 6° Balsam S82°W 17.47° to set N&T on Side 6° Balsam S82°W 17.47° to set N&T on Side 6° Balsam S82°W 18.40° to set N&T on Side 6° Balsam S82°W 18.40° to set N&T on Side 6° Balsam S82°W 18.40° to set N&T on Side 6° Balsam S82°W 18.40° to set N&T on Side	requirements of PA 74, Mi and 2 above were in conforthe current manual of sur Interior, Bureau of Land Mi corner points mentioned in of the Michigan Board of	ichigan PA of 1970, the corner points mentioned ormance with regulations and rules therefore as rervey instructions of the United States Departme anagement or by a decree of a Court of Law and/or lines 3, 4 and 5 above were in conformance with If Land Surveyors or by a Decree of a Court	at under in lines 1 quired in nt of the r that the the rules ow:
C-6 — Corner comm. to sections 7,8,17 & 18, T32N,R03E 1850 — GLO — Hiram Burnham — Set post for corner to sections 7,8, 17 & 18, T32N,R03E Aspen 12 S40°E 28			11
C-6 — Corner comm. to sections 7,8,17 & 18, T32N,R03E 1850 — GLO — Hiram Burnham — Set post for corner to sections 7,8, 17 & 18, T32N,R03E Aspen 12 S40°E 28			
1850 – GLO – Hiram Burnham – Set post for corner to sections 7,8, 17&18. Aspen 12 S40°E 28			
Aspen 12 S40°E 28 Y. Prine 10 N20°E 30 1986 – L.C.R.C. L.001, p.399 – Delmer E. Porter P.S.# 15410 Found 2° pipe in Concrete (M. Schaaf) N20°E 38.28' 16° Spruce N64°E 17.19' 8' Maple S31°W 33.45' NE Cor. Cabin B. Description of corner evidence found and/or method applies in restoring or re-establishing corner: C-5 – Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2° Pipe Per L.C.R.C. L. 001, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. C-5 – Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2° pipe Witnesses: N15°E 38.43' to set N&T on E side 26° Spruce S63°E 25.88' 10° Balsam S80°W 23.40' 10° Balsam	C-5 - Corner comm. to	sections 7,8,17 & 18, T32N,R03E	<u>C-6</u> – ¼ Corner comm. to sections 17 & 18, T32N,R03E
Hemlock 10 East 02 1986 – L.C.R.C. L.001, p.399 – Delmer E. Porter P.S.# 15410 Found 2° pipe in Concrete (M. Schaaf) N20°E 38.28¹ 16° Spruce N64°E 17.19' 8' Maple S31°W 33.45' NE Cor. Cabin B. Description of corner evidence found and/or method applies in restoring or re-establishing corner: C-5 – Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2° pipe Per L.C.R.C. – L. 001, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-5 – Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2° pipe Standard DNR Monument Witnesses: N15°E 38.43' to set N&T on E side 26° Spruce S63°E 9.10' to set N&T on E side 26° Spruce S63°E 9.10' to set N&T on E side 26° Spruce S63°E 9.10' to set N&T on E side 11° Maple Set blue post 1' North *Witness of previous record Hemlock 10 East 02 1986 – L.C.R.C. L. 001, p.399 – Delmer E. Porter P.S.# 15410 Set 2' Capped iror not by single prop measurement S85°E 18.26° 14° Spruce S87°E 18.26° 14° Spruce S87°E 18.26° 14° Spruce S80°W 23.40' 10° Balsam S80°W 23			
Found 2" pipe in Concrete (M. Schaaf) N20"E 38.28' 16" Spruce N64"E 17.19' 8" Maple S31"W 33.45' NE Cor. Cabin 8. Description of corner evidence found and/or method applies in restoring or re-establishing corner: C-5 — Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2" Pipe Per L.C.R.C. — L. 001, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-5 — Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2" pipe Standard DNR Monument Witnesses: N15"E 38.43" to set N&T on R side 26" Spruce Sa3"E 9,10" to set N&T on N side 4" W. Pine S49"W 46.48" to NE Corner Brick Chimney NS2"W 48.55" to set N&T on R side 11" Maple Set blue post 1' North *Witness of previous record Set Nath Addition and the proper measurement S85"E 25.08" to set N&T on N side 14" Balsam 14" Balsam *N83"W 23.34' to set N&T on N side 6" Balsam 18" S88"W 23.34' to set N&T on N side 6" Balsam 18" S89"W 23.34' to set N&T on N side 18" Balsam 18" S82"W 17" to set N&T on N side 18" Balsam 18" S82"W 23.34' to set N&T on N side 14" Balsam 14" Balsam Set blue post 1' North *Witness of previous record. *Witness of previous record. *Witness of previous record.			
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner: C-5 - Corner comm. to sections 7,8,17 & 18, T32N,R03E Found 2" Pipe Per L.C.R.C L. 001, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-5 - Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2" pipe Standard DNR Monument Witnesses: N15°E 38,43' to set N&T on E side 26" Spruce S63'E 9,10' to set N&T on N side 4" W. Pine S62"W 46,48' to NE Corner Brick Chimney N52"W 48,55' to set N&T on E side 11" Maple Set blue post 1' North *Witness of previous record Witness of previous record Witness of previous record *Witness of previous record. *Witness of previous record. *Witness of previous record. *Witness of previous record.	Toda midition bloom proces beautiful bloom bea		Set a 1/2" Capped iron rod by single prop measurement
Found 2" Pipe Per L.C.R.C. – L. 001, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-5 — Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2" pipe Standard DNR Monument Witnesses: N15°E 38.43' to set N&T on E side 26" Spruce S63°E 9.10' to set N&T on N side 4" W. Pine S49°W 48.55' to set N&T on E side 11" Maple Set blue post 1' North *Witness of previous record Witness of previous record C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E	N64°E 17.19	9' 8" Maple	S48°W 8.57' 6" Balsam
Found 2" Pipe Per L.C.R.C. – L. 001, p.399. Accepted found pipe as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-5 — Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2" pipe Standard DNR Monument Witnesses: N15°E 38.43' to set N&T on E side 26" Spruce S63°E 9.10' to set N&T on N side 4" W. Pine S49°W 48.55' to set N&T on E side 11" Maple Set blue post 1' North *Witness of previous record Witness of previous record C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E Found ½" CIR Per L.C.R.C. — L. 001, p.399. Set a Standard DNR Monument . Accepted found CIR as the best available evidence for the position of the corner: C-6 — '/- Corner comm. to sections 17 & 18, T32N,R03E			
found pipe as the best available evidence for the position of the original corner. DNR Monument . Accepted found CIR as the best available evidence for the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-5 — Corner comm. to sections 7,8,17 & 18, T32N,R03E Added PS Cap #33981 to found 2" pipe Standard DNR Monument Witnesses: N15°E 38.43' to set N&T on E side 26" Spruce S63°E 9.10' to set N&T on N side 4" W. Pine S63°E 9.10' to set N&T on N side 4" W. Pine S63°E 25.34' to set N&T on N side 13" Balsam S62°W 17.47' to set N&T on S side 6" Balsam N52°W 48.55' to set N&T on E side 11" Maple Set blue post 1' North *Witness of previous record CARL Witness of previous record. CARL Witness of previous record.			
Added PS Cap #33981 to found 2" pipe Standard DNR Monument Witnesses: * N15°E 38.43' to set N&T on E side 26" Spruce S63°E 9.10' to set N&T on N side 4" W. Pine S49°W 46.48' to NE Corner Brick Chimney N52°W 48.55' to set N&T on E side 11" Maple Set blue post 1' North * Witness of previous record Carl T Manual August 100 Sections 17 & 18, T32N,R03E C-6 – 1/4 Corner comm. to sections 17 & 18, T32N,R03E Standard DNR Monument Witnesses: * N02°E 8.53' to set N&T on W side 6" Balsam 13" Balsam S62°W 17.47' to set N&T on S side 6" Balsam 14" Balsam Set blue post 1' North * Witness of previous record. Carl Kliskila LAND LAND	found pipe as the best available evidence for the position of		DNR Monument . Accepted found CIR as the best available
Added PS Cap #33981 to found 2" pipe Standard DNR Monument Witnesses: * N15°E 38.43' to set N&T on E side 26" Spruce S63°E 9.10' to set N&T on N side 4" W. Pine S49°W 46.48' to NE Corner Brick Chimney N52°W 48.55' to set N&T on E side 11" Maple Set blue post 1' North * Witness of previous record Carl T Manual August 100 Sections 17 & 18, T32N,R03E C-6 – 1/4 Corner comm. to sections 17 & 18, T32N,R03E Standard DNR Monument Witnesses: * N02°E 8.53' to set N&T on W side 6" Balsam 13" Balsam S62°W 17.47' to set N&T on S side 6" Balsam 14" Balsam Set blue post 1' North * Witness of previous record. Carl Kliskila LAND LAND	C. Description of monum	nent for corner and accessories established t	perpetuate locating the position of the corner:
Added PS Cap #33981 to found 2" pipe Witnesses: * N15°E 38.43' to set N&T on E side 26" Spruce S63°E 9.10' to set N&T on N side 4" W. Pine S49°W 46.48' to NE Corner Brick Chimney N52°W 48.55' to set N&T on E side 11" Maple Set blue post 1' North * Witness of previous record Standard DNR Monument Witnesses: * N02°E 8.53' to set N&T on W side 6" Balsam 13" Balsam S62°W 17.47' to set N&T on S side 6" Balsam 14" Balsam Set blue post 1' North * Witness of previous record. CARL KIISKILA LAND			
* N15°E 38.43' to set N&T on E side 26" Spruce S63°E 9.10' to set N&T on N side 4" W. Pine S49°W 46.48' to NE Corner Brick Chimney N52°W 48.55' to set N&T on E side 11" Maple Set blue post 1' North * Witness of previous record * N02°E 8.53' to set N&T on W side 6" Balsam 13" Balsam S62°W 17.47' to set N&T on S side 6" Balsam 14" Balsam S62°W 17.47' to set N&T on N side 14" Balsam 15" Balsam			
*Witness of previous record *Witness of previous record. Carl Fushula 4-18-18 LAND LAND	* N15°E 38.43' to s S63°E 9.10' to s S49°W 46.48' to l	set N&T on N side 4" W. Pine NE Corner Brick Chimney	*N02°E 8.53' to set N&T on W side 6" Balsam *S89°E 25.34' to set N&T on N side 13" Balsam S62°W 17.47' to set N&T on S side 6" Balsam
*Witness of previous record *Witness of previous record. Carl Fushula 4-18-18 LAND *Witness of previous record. LAND *Witness of previous record. LAND	Set blue post 1' Nor	th	Set blue post 1' North
Carl T Kuskila 4-13-18 CARL KIISKILA			* Witness of previous record.
LAND 1	0		CAPI CAPI
			LAND X

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURV