



FORESTRY DIVISION

### LAND CORNER RECORD

T\_25 NR 9E

						Alo	ona_			COUNT	Y
DESCRIPTION	OF	CORNER	Se	ction c	orner c	ommon to	Secti	ons 2	8,29,32,	33	
DESCRIPTION	OF	CORNER	MOM	NUMENT	r_l"_pi	pe, with	4" br	ass c	ap		
WITNESSES	то с	CORNER									
			8"	B. Oak		N44W	_ = _	921/2	links		
			_7_"_	R. Oak		S60W_	- = -	_47	links		
			5"	W. Oak	=_	_ S70E_	_ = _	57_	links		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by double proportionate measurement between corners 2 miles north, 1 mile south, 1 mile east, 2 miles west by Forestry Division survey crew. Could make no positive identification of government corner, although our point checks good with swamp edges east, west, north and possibly south which is quite indefinate.

Corner placed and witnessed May 8, 1958.

SURVEYORS SEAL

SIGNED leweth & Octlery REGISTERED LAND SURVEYOR





FORESTRY DIVISION

### LAND CORNER RECORD

T\_25 NR\_9\_E\_\_

		-	A	Lcona		COUNTY
DESCRIPTION OF CORNER	South .	T\2 co	rner com	mon to se	ctions_2	g_and 29
DESCRIPTION OF CORNER	MONUME	NT <u>T</u>	"x24" pi	pe		
WITNESSES TO CORNER						
	BT	7" J. :	Pine -	s 54 E	- 82	Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement by Forestry Division survey crew. Falls in open marsh, NW of small J. Pine island. Set mid-point, on line between section corner south and 1/4 corner north.

Corner was placed and witnessed May 27, 1958.

SURVEYORS SEAL

SIGNED Kenneth Joseph

ling DATE 6/5/57

CONS. 4047 4/56

## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

#### LAND CORNER RECORD

T 25 NR 9 E

		Alcona_	COUNTY
DESCRIPTION OF CORNE	R 1/4 corner	common to Sec	tions 28 and 29
DESCRIPTION OF CORNER	MONUMENT_1"	pipe_with 4"	brass cap
WITNESSES TO CORNER			
	6" Aspen	_ S 18 E	35½ links
	8" Aspen	s 70 W	30 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a partial resurvey of this township. Corner was established by proportionate measurement between section corners, since no positive identification of the government witnesses could be made.

Corner was placed and witnessed May 27, 1958.

SURVEYORS SEAL

SIGNED CENTELL J OSTLENE DATE 6/5/52



FORESTRY DIVISION

#### LAND CORNER RECORD

T 25 NR 9 E

			_ Alcona _	COUI	NTY
DESCRIPTION OF CORNER	North 1/	8 corner	common to s	ections 28 and	29
DESCRIPTION OF CORNER	MONUMEN	ITT" x2	+ <u>"_pipe</u>		-
WITNESSES TO CORNER					- 4
	BT	б" Марте	_N 29 E	_24 _ <u></u>	-
	BT	7" R. Oal	k s 60 W	46 Links	-
					-

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement, midpoint on line, between section corner north and 1/4 corner south, by Forestry Division survey crew while on a survey project in this area.

Corner was placed and witnessed May 27, 1958.

SURVEYORS SEAL

SIGNED LEWNETT JOSTHUS REGISTERED LAND SURVEYOR

DATE 6/5/18



FORESTRY DIVISION

### LAND CORNER RECORD

T\_25\_ NR\_9E\_\_\_

		Alco	ona	_ COUNTY
DESCRIPTION OF CORNER	Section corne	r common to Se	ections 20,21,2	8,29
DESCRIPTION OF CORNER	MONUMENT			
WITNESSES TO CORNER				
	_12" _R. Oak_	_ =S50W _	38_ link	<u>s</u>
	8" R. Oak	N44M _	$-\frac{90^{\frac{1}{2}}}{1}$ link	s

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by double proportionate measurement between corners 1 mile north, 1 mile east, 2 miles south and 2 miles west by Forestry Division survey crew. Could make no identification of original BT's. This point conforms more closely to the swamp edge north than a square concrete monument which is 1.02 chain south and 25 links east of our corner, by unknown surveyor and not of record. Did not seem justified in accepting this corner which makes the mile north 81.00 at the expense of the two miles south, when nothing definate could be found for government evidence.

Corner placed and witnessed May 9, 1958.

SURVEYOR'S SEAL

SIGNED REGISTERED LAND SURVEYOR

DATE \_6/6/58 \_