									Page	of		
USDA - Forest Service	FS-630	00-0020 Rev 01/1	7 1. FC	ORES	ST							
CONTRACT DAILY DIARY (Reference FSH 6309.32)			2. CO	TNC	RACT NO.							
3. PROJECT	<u> </u>											
4. CONTRACTOR					5. CONTRACTOR REPRESENTATIVE ON SITE							
6. GOVERNMENT OFFICIA	ALS ON SITE											
7. DATE	8. DAY OF WEEK	9. TIME ARRIV	ED 1	0. TI	ME DEPAR	TED 11. WEATH	IER					
12. TEMPERATURE °F.	F. 13. GROUND CONDITION				14. CON	TRACT TIME	15. DAYS USE	ED 16. COM	IPLETION D	DATE		
Min. Max. 17. TIME USED (%)	18. WORK COMPLETED					20. CONTRACTOR'S WORK - (X Appropriate Box)						
21. CHANGE ORDERS/AM	CHANGE ORDERS/AMENDMENTS ISSUED					NO Acceptable Unacceptable - Explain in narrative 22. WORK ORDERS ISSUED (Include SUSPEND/RESUME)						
23. MATERIALS FURNISHED 1	TO JOB SITE (Furnished By: G-	-Govt.; C-Cont.; S-Su	ıbcont.) →	+	24. LIST EC	QUIPMENT ON SITE ((Furnished by G-Go			→ → Hours Used	+	
25. LIST CONTRACT PAYM					26. WORK	CERS ON SITE				umber		
<u>Item</u> <u>Pr</u>		<u>Prep</u>	Subm	<u>it</u>		Classific	<u>ation</u>		PRIME	SUB		
27. GOVERNMENT PROVII	DED SERVICES ADEQUAT	TELY AND TIMEL	_Y									
YES 28. NARRATIVE REPORT	NO - Explain in narr											
		ı	·· - · -				T					
29. SIGNATURE 30. TITLE							31. ADDTL SPACE NEEDED (continued on 6300-21)					

FS-6300-21

FIELD REVIEW NOTES FOR GNA-Hiawatha-FY23-Project#1 [6/13/2024]

C-E 1/16th Corner S36

- BT's visible; check with Bearing & Distances stated on the sign
- located in a maintained yard, no visible encroachments NW

C-E 1/16th Corner S36 -> NORTH

- cleared and marked good
- Property corners at Castle Rock Lake Road visible
- (Started raining)

NE 1/16th Corner S36

• SW & NE BT's Checked; SW doesn't match distance stated on the sign

NE 1/16th Corner S36 -> WEST

- cleared and marked good
- Steep hill West of corner, East of road
- Found monuments East & West of road as noted on CSM
- Marked OK west of road; OK on rail placement at Tops & Toes

C-N 1/16th Corner S36

• SW & NW BT's Checked

MOVE (still raining)

Spot Check - Castle Rock Road / Forest Road 3722 @ W 1/16th line

- opened and marked good N & S
- Appears to be previously marked, existing markers online

MOVE (still raining)

Spot Check - Forest Road 3722 @ W 1/16th line

• cleared and marked good N & S; visible markings at tops & toes

MOVE (still raining)

Spot Check - Forest Road 3722 @ E-W 1/4 Line -> WEST

• cleared and marked good E & W; visible markings at tops & toes

C 1/4 Corner S36

- NE & SE BT's checked
- Lines cleared and marked well in all four cardinal directions



FS-6300-21

GENERAL COMMENTS:

Good on number of marks. Cutting and clearing appears to be Good to Excellent. A good number of reference marks and a good number of line trees. Excellent job moving brush to USFS lands.

A few areas I would point out for FUTURE PROJECTS IN THIS REGION:

- Aerosol Paint is acceptable; brushed on paint isn't required
- ALL witnesses should be marked with a Chest and Stump Blaze; even those on Private Lands
- Per specifications 3136 & 3136.1 = "Section subdivisional and other corners will be marked with a monument that meets State of Michigan requirements (½ inch (#4) by 30" length rebar with a 3 ¼ inch aluminum cap monument) and will be supplied by the Contractor and monument type will be included in all drawing legends." AND "All section subdivisional corners monumented under this contract using a monument provided by the contractor shall be stamped in accordance with the 2009 BLM Manual of Instructions (pages 113-116)."

