



Facility Summary Report

Building Name: Tree Improvement Center/Cone Processing Building

DNR TagID#: **84162**
 Facility Location: **Tree Improvement Center**
 Inventory Status: **Verified**
 Inventory Date: **07/14/2016**
 Managing Agency: **Forest Resources**
 Facility Type: **Storage/Workshop**
 Facility Use: **Storage/Warehouse**
 Building Status: **Active**
 Building Manager: **Sheila Clark (906-341-2518)**
 Building Telephone: **810-229-9152**
 Building Fax: **810-229-9152**
 Building Address: **Unknown**
 Construction Date: **04/25/1995**
 Square Footage: **3,200**
 Historical Cost: **\$15,000**
 Leased/Own: **DNR-Owned**



Employees at Location: **No**
 Vacant Workstations: **None**
 Electricity: **Yes**
 Water: **No**
 Heat: **No**
 Storage Space: **No**

MISC. COMMENTS

LOCATION INFORMATION

COUNTY NAME	TIER/RANGE	TOWNSHIP NAME	SECTION	QQ	Q	LOTS PAR ID	LATITUDE	LONGITUDE
Livingston	01N - 05E	HAMBURG	04	SW	NE	164020	42.50694531	-83.85769672