



# Facility Summary Report

*Building Name: Gladwin Wildlife Field Office/Gladwin Warehouse*

DNR TagID#: **85104**

Facility Location: **Gladwin Wildlife Field Office**

Inventory Status: **Verified**

Inventory Date: **05/25/2017**

Managing Agency: **Wildlife**

Facility Type: **Storage/Workshop**

Facility Use: **Storage/Warehouse**

Building Status: **Active**

Building Manager: **Glenn Lampela (989-445-0213)**

Building Telephone: **989-426-9205**

Building Fax:

Building Address: **Unknown**

Construction Date: **05/01/2012**

Square Footage: **1,456**

Historical Cost: **Unknown**

Leased/Own: **Leased**

Employees at Location: **No**

Vacant Workstations: **None**

Electricity: **Yes**

Water: **No**

Heat: **No**

Storage Space: **Yes - Cold**

**NO PHOTO AVAILABLE**

## MISC. COMMENTS

## LOCATION INFORMATION

COUNTY NAME	TIER/RANGE	TOWNSHIP NAME	SECTION	QQ	Q	LOTS PAR ID	LATITUDE	LONGITUDE
Gladwin	18N - 01W	BUCKEYE	06	NE	SW		43.97888800	-84.48135500