



B.M. NO. 1 = 100.0 - CROSS ON UNDERSIDE OF SLAB, SO. SIDE OF W. END OF BRIDGE
 WATER SURFACE ELEVATION = 97.2
 3/2/62

INSTITUTE FOR FISHERIES RESEARCH
 DIVISION OF FISHERIES MICHIGAN CONSERVATION DEPT.
 LAKE INVENTORY MAP
MAPLE LAKE
 AREA 172 ACRES
 MARGINAL SURVEY AND SOUNDINGS BY
 LAKE & STREAM IMPROVEMENT SECTION 2/26-28 & 3/1-2/62
 VAN BUREN COUNTY T. 3 S., R. 14 W., SEC'S. 1, 12



B.M. NO. 2 = 100.0 - CROSS IN SO. END OF FOOT BRIDGE ABUTMENT
 WATER SURFACE ELEVATION = 99.2
 3/2/62

- LEGEND**
- BOTTOM**
 - Sand (stippled pattern)
 - Organic (white)
 - Sand & Organic (cross-hatched)
 - OUTLINE & CONTOURS**
 - Shoreline (solid line)
 - Breakwater (dashed line)
 - Contours (dashed line with depth label)
 - SHORE FEATURES**
 - Steep Slope (three horizontal lines)
 - Wooded (circle with 'W')
 - Partly Wooded (circle with 'PW')
 - Brush (circle with 'B')
 - Marsh (circle with 'M')
 - Building (solid black rectangle)
 - Boathouse (square with 'X')
 - Dock (solid black rectangle)
 - Dam (thick solid line)
 - Improved Road (double line)
 - Bridge (line with cross-ticks)
 - Inlet (line with arrow pointing in)
 - Outlet (line with arrow pointing out)



WL