

RF

MAR 03 2000 LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

SECTION

1999 Alcona County Remonumentation

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T.25N N. S., R.5E E. W.	A-10
2. PROPERTY CONTROLLING IN SECTION _____	, T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

Alcona County
 Remonumentation
 Liber 2 Page 16

Filed for Record in
 ALCONA COUNTY MICHIGAN
 DORIS A GAUTHIER
 On 12-17-1999 At 10:32 a
 LAND CORNER 9.00

REGISTER OF DEEDS STAMP AND
 FILING NUMBER

I, John F. Oliver do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Dec. 8, 1999, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-10: 1838: GLO survey by L. Clason - set post and referenced
 1929: dependent resurvey by G. Veal - set iron post 3' long,
 2" dia. 27" in ground with brass cap

APPROVED LAND CORNER
 P A 345 of 1990
 ALCONA COUNTY
 Date 11/30/99
 County Rep [Signature]

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-10: no witnesses or corner found

 no evidence recovered from GLO survey of 1838

 corner was established by single proportionate method
 between existing corners A-11 and A-9

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-10: placed 1/2" rod with aluminum cap
 referenced:
 12" beech / N 30°E / 4.56' to nail
 12" beech / N 65°W / 37.25' to nail
 12" maple / S 02°W / 37.93' to nail
 12" oak / S 50°W / 70.05' to nail



SIGNED BY [Signature] DATE Dec. 8, 1999
John F. Oliver
 SURVEYOR'S MICHIGAN REGISTRATION NO. 19840 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
 CHIEF OF SURVEY PARTY
 APPROVED AND SIGNED BY _____ DATE _____
 MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____