## 1995 Alcona County Remonumentation Corner

Alcona Count		
Remonument	ation	-
	_Page <u>_ /                                   </u>	

## LAND CORNER RECORDATION CERTIFICATE

For co	Filing Requirement of Act 74, Mich. P.A. 1970										RECORDED									
	Alco	ona	_ Lo	cated In:		(	Corner Cod	le#				114	VV	, IV D	L 19					
<ol> <li>Pro in :</li> <li>Missing :</li> </ol>	(County)  ablic Land Surve  operty Controlli  Section  scellaneous  operty in Sectio	ey ng	S S	T 25N T T T T T T	R 6E R R R R R R	- - - - -	K-8	PROVED LAND CORNER P A 345 of 1990 A CONA COUNTY	ate 7-2/95	JUL 21 2 12 PM '95  Jul 21 2 12 PM '95  Jul 21 2 12 PM '95  ALCONA COHART MICHIGAN  gister of Deeds Stamp & File Number										
4 1	4.61 '	, D	and all Di	1-4				¥	0						*****					
	t No ivate Claims									~ A	В	C	D £	F.	G	<del>     </del>	J.	K.	i	
J. FII	ivate Clairis									- 2	é [	<del>- </del> ;	ļ —	-4-		· a —	<u></u>	_	-	
					•					3				4	<del> </del>	+		_	_	
										4	— <u>?</u> —			— <b>9</b> -		10	11		- 1:	
ı,Dav	id B. Gut	<u>chrien</u>	a field su	urvey on _		May	7 25	, 19 <u>95</u>		5	_					1-1	$\dashv$		_	
do here	by certify that ur	ider require	ments of	f P.A. 74, N	viichigan P.A. o	of 1970	), the comer	points men	ntioned	6	 - <del></del> 18		7—	—16·	_	15-	 14		-15	
	1 and 2 above w Lof survey insti									7		_		<u> </u>		$\perp$	_	_	_	
	•				•		-			8	19-		0—	 21·		22—	 23·	_	2	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a									Ĩ	$oldsymbol{\perp}$	_]									
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found						10			9			27								
•	ressed below:									11	_Ĭ_		Ĺ						Ĵ.	
NOTE:	Not more that on this certific		's, all in	the same	e town and ra	ange, I	may be rec	orded		12		,							_ ]	
	or and octain	Julio.								13						الله			[	
A. De	escription of or	iginal mo	nument	and acc	essories and	or su	bsequent	restoratio	n:											
1	844: G.L. Beed				.H. Mull 16 / Bet					efe	rer	ce	f							
1	904: Surv	ey by	Edw	. Chaj	pelle -	Ced	lar Pos	t				. •								
1	909: Surv	ey by	And:	rew J	. Freer	- 0	rey bo	ulder	14 x	12	x 1	.1 .	inc	che	S					

1989: Survey by D.R. MacNeill and Assoc. - Set 1" Pipe

1993: Survey by D.R. MacNeill and Assoc. - Found 1" Pipe

1959: Survey by R.S. Scott Eng. Co. - Set Railroad spike

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Found Iron Spike on the centerline of Hoskins Road to the East and 2.5 Ft. West of the centerline of Ford Road.

Survey & AEMONUMENTATIO"

OCT 2 6 1995

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: Set a 1/2" x 24" Iron Rod with a brass cap stamped to identify the corner placed in a monument box. Referenced: N50°E - Fe. Cor. Post - 49.78 Feet

S45°E - Fe. Cor. Post - 47.18 Feet West - Fe. Cor. Post - 36.85 Feet

S65°E - 12" Aspen - 74.91 Feet

liter Signed by 22435 Surveyor's Michigan License No. PROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

DSURVEY