1995 Alcona County Remonumentation Corner

APPROVED LAND CORNER
P A 345 of 1990
ALCONA COUNTY
Date. 1-21-95
County Rep. 6 . [. C.

Filing Requirement of Act 74, Mich. P.A. 1970 County Rep. 2 1 PECORDED										<u>. </u>	:
Fo	r corners in	FILE	Filing Requirement of Act /				RECOF	(DED			
_	Alcona (County)	Located I	n:	Corner Code #	1	Alcona Remo	ni iman	เลนเดเ	1	13	1
	,				1 1	Liber-	71 7	Pag	20.05		-
1.	Public Land Survey	T 25	N_ R_6E_	L-13		501-	<u> </u>	- 74 ()	1 55		
		Τ	R		1	1		ð			
			R	·	اه ا	Dan	ie a	122	Line	>	
			R		County umentation Page	<i>V</i> -	REGISTER	C 13- 10: 1.4/.	3		
2.	Property Controlling	ST			거뜌요.	ALE	Tribbut even				
_	in Section	ST			털털						
3.	Miscellaneous	ST			희물 뉴	legister of l	Deeds S	tamp 8	k File i	Numb	er
	Property in Section	S T	n	 (얼률니	3.2					
4	Lot No.	Recorded Plat			Alcona Remon						
	Private Claims							F -	G н	11	K
-					AET.	6	 \$	╂┷╅┷	 -		
						3		+			
						4 <u>├</u> ─र्	— - - - - - - - - - - - - - - - - - - -	╀-∳	10-	+1;1-	1
ı,D	IDavid B. Guthriein a field survey on June 2, 1995,							 	 	+	-
	do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned										
	in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land										
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and						8 - 19	20-	21-	-22-	23-	2
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a						9		↓ .↓.	 	4-4-	
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:							29—	 28	 27	26-	2
	•					11				4-4	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						12 -31	32-	 33	34-	35-	3
	on ano consider	· ·				13		1 1			

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1838: G.L.O. Survey by Lewis Clason Set post and referenced Y.Pine 16 N75W 66
 - 1967: Survey by R.S. Scott Eng. Co. Found 1927 Gov't Cor.
 - 1989: Survey by D.R. MacNeill and Assoc. Found monument
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1995: Found 1" Iron Pipe with brass cap.

S YEVAUS REMONUMENTATIO

OCT 2 6 1995

COMMISSION

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - 1995: 1" Iron Pipe with brass cap stamped to identify the corner

Referenced: S20°E - 12" R.Pine - 36.06 Feet

S16°W - 8" R.Pine - 30.30 Feet

N72°E - 10" Jack Pine - 53.63 Feet N22°W - 10" Oak - 45.91 Feet North - 3/4" Iron Pipe - 33.00 Feet

OF MICH GLITTHRIE

Surveyor's Michigan License No.

22435

REVISED MAY 14, 1975 REVISED JAN., 1983