

REMONUMENTATION

FEB 22 1996

COMMISSION

ALCONA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alcona County
Remonumentation
Liber 1 Page 149

For corners in

| | | |
|---------------------------------------|--------------|---------------|
| <u>ALCONA</u> (County) | Located In: | Corner Code # |
| 1. Public Land Survey | T 25 N R 7 E | C-3 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

APPROVED LAND CORNER
P.A. 345 of 1990
ALCONA COUNTY

Date: _____
County Rep: E.T.L.

RECORDED

DEC 20 4 43 PM '95

James A. Bantier
REGISTER OF DEEDS
ALCONA COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, WILLIAM E. WOODS, in a field survey on 12-12-, 1995 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | | | | | | | | | | | | |
|----|----|----|----|----|----|----|---|---|---|---|---|---|
| A | B | C | D | E | F | G | H | I | J | K | L | M |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | | |
| 3 | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | |
| 5 | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | |
| 7 | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | |
| 9 | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | |
| 11 | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | |
| 13 | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

1844: JAMES MULLETT SET POST.
W.PINE 28" S34°E 32
BEECH 9" N69°W 18

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1928: GUY R. VEAL SET 2" PIPE WITH BRASS CAP.
W.PINE STUMP 25" S282 22.20
W.PINE STUMP 36" N20E 55 LKS.
IRON BAR S62°W 1.90 CHS.

1982: ROBERT A. GRIFFIN FD. 2" PIPE WITH BRASS CAP.
MAPLE 8" S08°E 48.35
MAPLE 8" S86°W 67.38
MAPLE 15" N12°W 4.98
CEDAR POST SOUTH 1.80'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995 REMONUMENTATION WILLIAM E. WOODS P.S. 25882

REMON TO USE POSITION ESTABLISHED BY GUY R. VEAL
24" POPLAR S73°W 29.43 24" POPLAR S10°W 22.80
P.P. S85°E 43.18 22" MAPLE "BEARING TREE" M55 4.

Signed by William E Woods
Surveyor's Michigan License No. 25882

Date 12-20-95

