1997 Alcona County Remonumentation

	LAND COR	NER RECORDA	NTION CERTIFIC	ATEAICONA COL	antation
For corners in	Filing Requ	irement of Act	74, Mich. P.A. 1	970Remonume	Page 225
Alcona	•		<u> </u>	,	Approximation of the contract
(County)	_ Located in:	Corner C	°°E52 \	0500	nnrn
Public Land Survey	T 25N R 08E	F07		RECO	The state of the s
1. Fublic Land Survey	T R		\$ 00t C	•	and the state of t
	T R			a Aus IB I	50 fil '97
÷	TR			r	55 III 61
2. Property Controlling	S T R S T R			A Libraria	1 House
in Section 3. Miscellaneous	STR		PPR	الشمطل المسلكة	is Stamp & File Number
Property in Sec.	\$ T R		₹ □	-negister of beet	ia arquith a Lua wounder
	corded Plat			A B C	DEFGHIJKL
5. Private Claims					5
				3	
Wayne T. Lewis	June	26	07	4	8 9 10 11 11
<u> </u>	in a field survey on		, 19 9/	5	
do hereby certify that under requi	rements of P.A. 74, Michigan P conformance with regulations	P.A. of 1970, the core and rules therelo	ner points mentioned re as required in the	6 - 18	17161514
current manual of survey instruct	tions of the United States Dep	partment of the Inte	erior, Bureau of Land	i 7	╎╌╏┈╪┈╏┈╏╌╏╸╏╸ ┤
Management or by a decree of a C above were in conformance with	Court of Law and/or that the co the rules of the Michigan Boar	rner points mentior rd of Land Survevo	red in lines 3, 4 and 5 rs or by a Decree of a	. I T	20 - 21 - 22 - 23 - 2
Court of Law; established, re-	established, monumented, r	re-monumented, r	ecovered, found as	, 1	
expressed below:	11 * . Al		h =	10 30	2 9 28 27 25 25 2
NOTE: Not more than 4 cor on this certificate.	ners, all in the same town	and range, may	be recorded	12 31	3 3 3 3
. Oil tills solitifeste.				13	
A. Description of original mo	onument and accessories	and/or subseque	ent restoration:		
1843: GLO 1900: County Surveyor	Set post. Witnesses	Given: Cedar 6	S 2 E 22, Remloc	ck 18 N 35° E 16	• • •
1973: Richard Miller, P.S.	Cedar post. No monumentation or w	itnossos divon			
1973: Richard Miller, P.S.	Liber 1 CRC, page 58 -	Set 3/8" rod w/c	ap midway in stra	ight line. Witnes:	ses given: Due North 33.0
	3/8" Rod, Due South	31.95' Fence Po	st, S 60 30' W 12	2" Birch	3
				•	
B. Description of corner evid	dence found and/or metho Found 1/2" rered midw	nd applied in rest way and on line b	oring or reestablis etween R=7 and C=	shing corner: 7	' South of road centerline
	and 1' West of fence		chacon n i min n	. Corner raris :	. Porter of Load Delicetities
SURVEY &					•
REMONUMENTATION	NC				
MAR 0 4 1998					Will be seen as a second of the second
٠.					
SECTION	•		•		
OLOTOR					
					the corner
C. Description of monument 1997:	for corner and accessorie	es established to	perpetuate locati	ng the position of	on 1/2" rerod in place of
1,577	existing 1/2" rerod in		orned remonumence	cton 2, prass cah	ou 1/5, recor to brace or
OF MICE	,,	•			
WELL WITH THE PARTY OF THE PART	Witnesses given:			•	•
S WAYNE T.	N 25° W 43.82' 10" F N 60° E 69.80' 12" 7				
* LEWIS PROFESSIONAL SURVEYOR	S 25° W 55.36′ 6″ Ba		•		
		r Pole			
NO. 41922		•			
41922 SET					•
41922 SIGNAL SUMMER OF STREET		,			
91	-/		August	13, 1997	
Signed by	12000		Date		
Surveyor's Michigan License	No		FDI	IM APPROVED BY MICHIGAN K	TATE BOARD OF LAND BUNVEYONS, JAN. 94. REVISED MAY 14.
					. NAL GASIYAN