## SURVEY & REMONUMENTATION

## 1997APA16404999ounty Remonumentation

	LAND CORNER	RECORDATION CERTIFIC	UCONE UUU 9Mundana CATE	Midian
SECTION	Filing Requiren	nent of Act 745, Mich. P.A.	1970 ther	Page 23/
For corners in	,	<b>州</b>	RECOR	
Alcona	Located In:	Corner Code Set	KECOM	.1
(County)		262 <sup>-</sup> 6		•
1. Public Land Survey	7 25N R 08E	HO9 N TO SUN	hug 18 2	co PH <b>'97</b>
	T R	7.5₹	HUG TO Z	CO III - V
	T R		,	,
•	T R			4-11
	TR	Date ALC	REGISTER	OF DEEDS
in Section S _	r R r R	<u> </u>		
	T R		Register of Deeds	Stamp & File Number
Troperty in dec.				· · · · · · · · · · · · · · · · · · ·
4. Lot No, Record	ed Plat		A B C D	EFGHIJK
5. Private Claims		· · · · · · · · · · · · · · · · · · ·	[]	
			2 - 6 5 -	1-1-1-1-2-1-
			3	<del>1                                     </del>
Wayne T. Lewis	field survey on	, 97	5 7 8	9-10-11-1
do hereby certify that under requirement	ents of P.A. 74, Michigan P.A. of	1970, the corner points mentions		
in lines 1 and 2 above were in confo	rmance with regulations and	rules therefore as required in th	ie - 18-17-	16-1-15-14
current manual of survey instructions Management or by a decree of a Court	of the United States Departm of Law and/or that the corner r	ent of the interior, Bureau of Lar points mentioned in lines 3, 4 and	·	
above were in conformance with the r	ules of the Michigan Board of L	and Surveyors or by a Decree of	a 9 19 20	
Court of Law; established, re-estal expressed below:	blished, monumented, re-mo	numented, recovered, found a	10 30 29	
NOTE: Not more than 4 corners	all in the same town and	rance may be recorded	11	
on this certificate.	i, air in the same tomi bild	inige, hipy be recorded	12 31 32	33 34 35
			13	
<ul> <li>A. Description of original monur</li> </ul>	nent and accessories and/o	or subsequent restoration:		
1843: GLO		n: Cedar 9 N 65° E 11, Ced		N 7-1/0 <sup>4</sup> 7 50
County Surveyor 1973: James Campbell, P.S.		ine Stump 22 S 11-1/2°W 48 : N 30°W 65.03′ Power Po		
1773. Dames Campbell, 1.3.	I tibe: witherpes diven	. 11 JU W 03.03 TOWEL TO	16, 5 05 # 59.25	IONET LOTE
				- ,
		,	•	. •
			•	
				•
B. Description of corner evidence	ce found and/or method ap	plied in restoring or reestabl	ishing corner:	
1997:	Found 1/2" rerod 4' South	of road centerline and 1.5'	West of fence to the	North
			•	•
•.				
		•		
				•
				•
C. Description of monument for	corner and accessories es	tablished to perpetuate local	ting the position of th	e corner:
1997:		ped Alcona County Remonumenta	tion 3" brass cap on e	xisting 1/2" rerod in
	box.			
E OF MICHINA	Witnesses given:			
S WAYNET	S 60' W 94.15' 12" Whit	e Pine		
* LEWIS	S 03' W 34.70' Power Po	le		
PROFESSIONAL SURVEYOR SURVEYOR	North 33.00' 1/2" Rerod			
	N 25 W 70.90' Power Po		•	
41922	N 10' W 87.15' 8" Cedar			
PESSIONAL MARKET				
Continue	_			
91 -	t. L.	Augus Date	st 13, 1997	
Signed by	41922			
Surveyor's Michigan License No.	11/00	p	OBM APPROVED BY MICHIGAN STAT	E BOARD OF LAND BURYEYDAR, # REVISED N.