

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

1998 Alcona County Remonumentation

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25N N. S., R. 8E E. W.	J-11
2. PROPERTY CONTROLLING IN SECTION	, T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	, T. N. S. SURVEY & REMONUMENTATION	
4. LOT NO.	, RECORDED PLAT	NOV 25 1998
5. PRIVATE CLAIMS		

SECTION

Alcona County Remonumentation Page 306

APPROVED LAND CORNER  
P.A. 345 of 1990  
ALCONA COUNTY  
Date 9/22/98  
County Rep D. J. [Signature]

Filed for Record in  
ALCONA COUNTY MICHIGAN  
DORIS A GAUTHIER  
On 10-21-1998 At 11:22:03 a  
LAND CORNER 9.00  
DR

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, John F. Oliver do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Oct. 5, 1998, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

J-11; 1843: GLO survey by J. Mullett - set post and referenced

1956: survey by MDOT for M-171 Hwy - corner is shown on Plans with a tie from M-171 centerline

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-11; found R.R. spike in center of road - MDOT tie from Plans from K-11 is very good

existing fences North and South


accepted as the true location for the corner

no evidence recovered from GLO survey of 1843

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-11; set 1/2" bar with brass cap in a pavement box referenced:

pow. pole / S 5°W / 41.55 ft  
12" Cedar / N 20°E / 52.63 ft  
11" Cedar / N 78°E / 123.55 ft  
5" Spruce / S 55°W / 83.32 ft  
existing fence lines run North and South from the corner



SIGNED BY John F. Oliver DATE Oct. 5, 1998  
SURVEYOR'S MICHIGAN REGISTRATION NO. 19840 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_