

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

1998 Alcona County Remonumentation

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 25N N. S., R. 8E E. W.	K-5
2. PROPERTY CONTROLLING IN SECTION	, T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	, T. N. S., R. E. W.	
4. LOT NO.	, RECORDED PLAT	
5. PRIVATE CLAIMS		

APPROVED LAND CORNER  
P A 345 of 1990  
ALCONA COUNTY

Date 9/22/98  
County Rep D. M. Oliver

Filed for Record in  
ALCONA COUNTY MICHIGAN  
DORIS A GAUTHIER  
On 10-21-1998 At 11:21:33  
LAND CORNER 9.00  
OR

Alcona County  
Remonumentation  
Page 299  
Libel

**SURVEY &  
REMONUMENTATION**

**NOV 25 1998**

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

### SECTION

I, John F. Oliver do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Oct. 6, 1998, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

#### A. Description of original monument and accessories and/or subsequent restoration:

- K-5: 1843: GLO survey by J. Mullett - set post and referenced
- 1956: survey by MDOT for M-171 - cor. is shown 0.61 ft East of centerline
- 1985: survey by NE Surveys - cor. shown as found monument box


#### B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- K-5: found pavement box with 1/2" rod and cap distances and alignment are compatible with MDOT data from 1956 Plans. Accepted as the correct location for the corner
- no evidence recovered from GLO survey of 1843

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- K-5: placed brass cap on the 1/2" rod in the pavement box referenced:

SE cor. headwall / N 80°E / 40.55 ft  
pow. pole / S 43°E / 91.35 ft  
8" w. Pine / S 60°E / 198.00 ft  
NW cor. headwall / S 13°W / 249.21 ft



SIGNED BY John F. Oliver DATE Oct. 6, 1998  
SURVEYOR'S MICHIGAN REGISTRATION NO. 19840 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_