MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_25 NR & E___

		Alcone		COUNTY
DESCRIPTION OF CORNE	R 1/4 corner o	common to Section	ns_19_e	ng _20
DESCRIPTION OF CORNE	R MONUMENT 1	" pipe with 4"	brase_c	<u>ap</u>
WITNESSES TO CORNER				
	4" Belsam	<u>-</u> 845W		65 <u>‡</u> linkв
	14" Y. Pine	stub - 858E	-	9 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners by Forestry Division Land Surveyor while making a survey of Section 19. Could find no evidence of government BTs. This point checks acceptably with stream south.

Corner was placed and witnessed April 26, 1960.

SURVEYORS SEAL

SIGNED LAND SURVEYOR -- DA