## MICHIGAN DEPARTMENT OF CONSERVATION



FORESTRY DIVISION

## LAND CORNER RECORD

25 9E T\_24. NR \_ 9E \_ .

		Alcona	Toaco COUNTY
DESCRIPTION OF CO	ORNER Section corne	er_common_to_Sectio	ns 5,6,31,32
DESCRIPTION OF CO	RNER MONUMENT Let	t l" pipe in place	and took witnesses
WITNESSES TO COR	RNER		
	8" W. Pine	SIW	181 links
	7" _ WPine_	_ = _ N4E = _	167½ links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this area. Found 1" pipe previously established by unknown surveyor. This corner has been used in staking property in Iosco County and conforms fairly well with the government record to the stream east. Although the lengths of the 2 miles east and 1 mile west are made inconsistant, this corner was one of the few found to exist, and since it appeared to have been used in previous surveys, was accepted as valid in our survey. Found evidence of an old line running north from this corner for 1/4 mile.

Corner placed and witnessed May 7, 1958.

SURVEYORS SEAL

SIGNED Kuniel & Delling DATE 5/23/58