

**SURVEY &
REMONUMENTATION**

APR 24 1995

COMMISSION

1994 Alcona County Remonumentation Corner

Alcona County
Remonumentation
Liber 1 Page 107

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For corners in

<u>Alcona</u> (County)	Located in:	Corner Code #
1. Public Land Survey	T25N R 9E	I-4
	T ___ R ___	
	T ___ R ___	
	T ___ R ___	
2. Property Controlling in Section	S ___ T ___ R ___	
	S ___ T ___ R ___	
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	
	S ___ T ___ R ___	

APPROVED LAND CORNER
 P.A. 345 of 1990
 ALCONA COUNTY
 Date 12-21-94
 County Rep. E.T.L.

DEC 21 2 08 PM '94

David A. Guthrie
REGISTER OF DEEDS
ALCONA COUNTY MICHIGAN

E.T.L.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1					
3											
4	7	8	9	10	11	12					
5											
6	18	17	16	15	14	13					
7											
8	19	20	21	22	23	24					
9											
10	30	29	28	27	26	25					
11											
12	31	32	33	34	35	36					
13											

David B. Guthrie in a field survey on August 15, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1843: G.L.O. Survey by Mullett & Burt - Set Post and Referenced Y. Birch 8 - S35W 13 / Cedar 8 - S32E - 15
- 1907: Survey by Edw. Chapelle Sr. - Found Cedar Post
- 1958: Survey by Carl R. Small - Plat of Supervisor's Plat of Sterling's Resort
- 1959: Survey by Carl R. Small - Amended Plat of Supervisor's Plat of Sterling's Resort
- 1963: Survey by S.A. Tokoly - Plat of Greenbush Shores

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found 3/4" Iron Rod

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994: Replaced with a 5/8" Iron Rod with a 3" Aluminum Cap stamped to identify the Corner.
Referenced -

- S74°E - 10" Cedar - 26.25 Feet
- N20°E - 7" Ash - 20.62 Feet
- S78°W - 12" Cedar - 19.27 Feet
- N45°W - 6" Cedar - 38.07 Feet



Signed by David B. Guthrie

Date Dec. 21, 1994

Surveyor's Michigan License No. 22435