Cons. 4047 4/56

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

25 9E T_ 24 NR 9E___

			Alcona	Iosco	COUNTY
DESCRIPTION	OF CORNER	Section corner co	ommon to Sec	ctions 4.5.3	2,33
DESCRIPTION	OF CORNER	MONUMENT_Drov	e 1" x 24" j	pipe 4" belo	w surface of road
WITNESSES 1	O CORNER _				 -
		9" Tamarack		<u>-</u> 323½	links
		Only tree near w	orth_noting	-	
		•			
				·	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by single proportionate measurement between section corners 1 mile east and 1 mile west. Could locate no previously established corner, nor evidence of government BT's.

Corner was placed and witnessed May 7, 1958.

SURVEYORS SEAL ...

SIGNED REGISTERED LAND SURVEYOR DATE 5/29/58