MICHIGAN DEPARTMENT OF CONSERVATION



FORESTRY DIVISION

LAND CORNER RECORD

25 9E T. 24 NR 9E

	Alcona - Iosco COUNTY
DESCRIPTION OF CORNER 1/4 corner common t	_
DESCRIPTION OF CORNER MONUMENT_Drove 1	" x 24" pipe 4" below surface
WITNESSES TO CORNER	
_6"_J. Pine	N54M 98½ links
8 J. Pine	S19W - 72½ links
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS RESTORED.	LOCATED AND IDENTIFIED OR
This corner was established by proportic corners by Forestry Division survey crew while or original evidence.	mate measurement between section a survey project in this area. No

Corner placed and witnessed May 7, 1958.

SURVEYORS SEAL

SIGNED LEWILL J OSELLEY DATE _5/29/58