CONS. 4047 4/56

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_25 NR_9_#__

		Alcona	COUNTY
DESCRIPTION OF CORNER	North 1/8 corner	common_to_Sec	stions 32 and 33
DESCRIPTION OF CORNER	MONUMENT 1"x24	pipe	
WITNESSES TO CORNER			
	BT 7" J. Pine	- n 48 E	12½ links
	Br 6" J. Pine	- n 49	25 links
			-

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established at mid-point, on line between section corner north and 1/4 corner south, by Forestry Division survey crew while on a survey project in this area.

Corner was placed and witnessed May 27, 1958.

SURVEYORS SEAL

SIGNED LEMENTE SURVEYOR

DATE 6/5/57