

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 25. NR. 9. E. . .

----- Alcona ----- COUNTY

DESCRIPTION OF CORNER North 1/8 corner common to Sections 29 and 30

DESCRIPTION OF CORNER MONUMENT 1"x24" pipe

WITNESSES TO CORNER -----

BT 5" Cedar S 22 W 28 links

BT 12" Cedar N 14 W 85 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement, (mid-point on line), between section corner north and 1/4 corner south, by Forestry Division survey crew while on a survey project in this area.

Corner was placed and witnessed May 27, 1958.

SURVEYORS SEAL

SIGNED Kenneth J. Ostling DATE 6/5/58  
REGISTERED LAND SURVEYOR