MICHIGAN DEPARTMENT OF CONSERVATION



FORESTRY DIVISION

LAND CORNER RECORD

T_25_ NR_9E___

Alcona
DESCRIPTION OF CORNER _South 1/8 corner common to Sections 19 & 20
DESCRIPTION OF CORNER MONUMENT_1"_x 24"_pipe, only
WITNESSES TO CORNER
_6" _Cedar
6" Cedar - S25W - 20 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.
This corner was established by proportionate measurement between section corner south and 1/4 corner north, by Forestry Division survey crew. Old cutting edge now extends over 3 chains east to a blazed line, as noted in corner record for 1/4 between 19 and 20.
Corner placed and witnessed May 9, 1958.

SURVEYORS SEAL

SIGNED LEMELL SURVEYOR DATE 6/6/58