1998 Alcona County Remonumentation

S

For corners in Alcona

1. Public Land Survey

2. Property Controlling

Alcona County Remonumentation LAND CORNER RECORDATION CERTIFICATE Filed for Record in ALCONA COUNTY MICHIGAN DORIS A GAUTHIER On 11-05-1998 At 04:38 _ Page*_290* Filing Requirement of Act 74, Mich. P.A. 1970 Liber Located in: Corner Code # 04:38:31 pm. T_26NR 09E G-10 APPROVED LAND CORNER P A 345 of 1990 ALCONA COUNTY

in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	County Rep DDB tun Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L N 1 2 6 5 4 3 2 1
Nayne T. Lewis, in a field survey on 7-29, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
	11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

1843: J. MULLET - SET POST AND WITNESSED

1994: NORTHEAST LAND SURVEYS (BILL WOODS, P.S. AND JOHN OLIVER, P.S.) - FOUND SPIKE AND RECORDED SURVEY, NO WITNESSES GIVEN

1995: D.R. MACNEILL, P.S. - FOUND CAPPED REROD, NO WITNESSES GIVEN

SURVEY & REMONUMENTATION

NOV 2 5 1998

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SECTION

FOUND RAILROAD SPIKE ON NORTH/SOUTH ROAD C/L AND IN LINE WITH FENCE LINE EASTAWEST

THIS CORNER POSITION IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1998: PLACED 3" ALCONA COUNTY CAP, STAMPED TO INDENTIFY THE CORNER, OVER 1/2" REROD IN PLACE OF RAILROAD SPIKE, AND NEXT TO EXISTING 1/2" REROD FOUND UNDER SPIKE IN MONUMENT BOX

WITNESSES:

S 55° E 34.23' 12" WHITE PINE N 85° E 31.56' 5" JACK PINE N 40° E 56.36' 4" WHITE PINE WEST 62.95' POWER POLE

LEWIS PROFESSIONA SURVEYOR POFESSION MANUFESSION N

OF MICHIG

41922 Surveyor's Michigan License No.

November 2, 1998 Date