

DEC 1 6 1996

COMMISSION

1996 ALCONA COUNTY REMONUMENTATION CORNER Alcona County

Remonumentation __ Page -20 6 Liber

LAND	CO	RNE	R	RE	CO	R	D٨	T	Ю	N C	Ef	₹Т	IFI	CA.	TE
	-							_				_	_		

_		Filing Requir	rement of Act 74, Mich. P.A	4. 1970	•					
For	corners in <u>Alcona</u> (County)	Located In:	Corner Code #		REC	ORDE	D -			
1.	Public Land Survey	T <u>26N</u> R <u>9E</u> T R T R	Harrisville Twpo	POSITION	,	8 48				
i 3. I	Property Controlling n Section Miscellaneous Property in Section	T R S T R S T R S T R S T R			RESISTE COMPANY	AN ENE	753 128.49v		oer	
4. L 5. F	_ot No , Private Claims,	Recorded Plat			B C [) E F	G H	J 	ĸ	
1	Chomas L. Fabis	_, in a field survey on	November 8 ₁₉ 96	3 4	-78	9-	10-	11-		12-
do he n line nanu	ereby certify that under re es 1 and 2 above were in ual of survey instruction	equirements of P.A. 74, Michigan P conformance with regulations and ns of the United States Departr	A. of 1970, the corner points menti- rules therefore as required in the cu- ment of the Interior, Bureau of corner points mentioned in lines 3, 4	urrent 7	18 17	16-	15-	14-		13-
5 abo Decre	ove were in conformanc	e with the rules of the Michigan B	soard of Professional Surveyors or nted, re-monumented, recovered, for	by a g	30—29	2B-	27-	26-		25-
	on this certificate.	orners, all in the same town and		11	31 32	33-	34-	35-	3	 6-
A 1	Description of origina									

1843: G.L.O. Survey by Lewis Clason - Set post & referenced: (Hem. 12 - N33E - 9, W. Pine 24 - S32W - 14)

1901: County Survey by Ed Chapelle - Visited corner & referenced.

1971: Survey (Liber 147 Page 64) by James Scott - Found 1 1/2" Pipe.

1986: Survey (Liber 206 Page 974) by David Guthrie - Found 1" Iron Pipe.
1992: MDOT Survey by Clifford Lindgren - Found 1 1/2" Pipe and referenced.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" Pipe surrounded by broken glass at intersection of fences North & South and West. Also, found 3 existing witnesses.

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

			- ,	
1996:	Set 1/2" iron rod capped with a 3" corner, inside the existing 1 1/2"		cap stamped to	
	corner, marde the externing 1 1/2	r The.		A Min.
	References:			ARTE ATE OF MIC
				A
	Fe. Post - N10E - 38.35'			

10" W. Pine - S80W - 36.56" P. Pole - S10W - 28.00' 9" R. Pine - S25W - 37.00'

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

HOMAS L

FABIS

LAND SURVEYOR