## SURVEY & REMONUMENTATION

Surveyor's Michigan License No. 37278

MAR 0 4 1998	
SECTION 1997 Alcona County Remonumentation LAND CORNER RECORDATION CERTIF	FICATE ALCONA COUNTY
Filing Requirement of Act 74, Mich. P.A. For corners in	. 1970 Date 7/30/47
Alcona Located In: Corner Code #	County Rep. RECORDED
1. Public Land Survey  T27N R 7E T27N R 8E T R	Date 10-31-1997  REMON LIBER 1 PAGE 272  Time 3:30 PM  Doris A. Gauthier
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	Dorls A. Gauthier REGISTER OF DEEDS  Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
I, <u>Daniel T. Kibbe</u> , in a field survey on <u>April 1</u> , 19 <u>97</u> do hereby state that uncerequirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michig Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumental recovered, found as expressed below:	or the 5 10 17 16 15 14 13
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:  1838: GLO Survey by Lewis Clason - set post, referenced: Y. P.  1914: County Survey by Andrew J. Freer - fd. sleigh rail 38" 1.  and glass.  1916: County Survey by Andrew J. Freer - fd. sleigh rail 38" 1.  and glass.  1979: Survey by D.R. MacNeil - fd. P.K. nail, referenced: S 56  68.12' Fence post / N 30 W - 69.94' Fence Post.	ong, 4" wide, $\frac{1}{2}$ " thick with 4 holes ong, 4" wide, $\frac{1}{2}$ " thick with 4 holes
B. Description of corner evidence found and/or method applied in restoring or reestablishing 1997: Found P.K. nail over R.R. spike 1' east of N-S centerline on fence line west.	corner: e, in centerline east and
This corner position is compatible with county & local suits accepted as a careful and faithful perpetuation of the corner.	urveys. This corner position e position of the original
<ul> <li>C. Description of monument for corner and accessories established to perpetuate locating the 1997: Placed 3" Alcona County cap stamped to identify the corner monument box.</li> <li>Referenced: <ul> <li>N30°W - 72.9' - fd. nail in leaning fence post</li> <li>S35°E - 52.55' - fd. tag #15410 in Power Pole</li> <li>S60°E - 68.00' - set nail &amp; tag in fence post</li> <li>N20°W - 89.82' - set nail &amp; tag in gate post</li> <li>S60°W - 76.17' - fd. nail &amp; tag in power pole</li> </ul> </li> </ul>	position of the corner: er over ½" iron rod in  DANIEL T.  KIBBE LAND SURVEYOR
Signed by Date 0	No. 37278