## SURVEY & REMONUMENTATION

Surveyor's Michigan License No. 31591

A TOTAL OF THE PARTY OF THE PAR	`
MAR 0 4 1998 1997 ALCONA COUNTY REMONUMENTATION CO	Alcona County Remonumentation Liber / Page 247
LAND CORNER RECORDATION CERTIFICA	ATE I
SECTION Filing Requirement of Act 74, Mich. P.A.	20- N
For corners in	RECORDED
Alcona Located In: Corner Code # O	- DI/ W
A AN	580 August 25 1:00 P.M. 97
	8 ₹ P
1. Public Land Survey	A CONTRACTOR OF THE CONTRACTOR
· —— · —— / —— / —— / —— / —— / —— / ——	44 \$
T R R A-D Hawes Two.	A Sauther
2. Property Controlling S T R Hawes Two.	8 8 Duis a Starther
in Section S T R	REGISTER OF DEEDS
3. Miscellaneous S T R	Double of B. J. C. C. C. C. C.
Property in Section S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L h
5. Private Claims	2 6 5 4 3 2 1 3
	3
	4 7 8 9 10 11 12
I, Thomas L. Fabis, in a field survey on June 12, 19 97,	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land	7
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and	
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a	
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	11
on this certificate.	12 31 32 33 34 35 36
<ul> <li>A. Description of original monument and accessories and/or subsequent restoration:</li> <li>1838: G.L.O. Survey Lewis Clason Set post &amp; referenced: (Y. Pine 26 S48W 61, do 22 N62W 13).</li> <li>1973: Survey Liber 151 Page 251 James Scott Found ex. pipe.</li> <li>1979: Surveys L.173 P's. 965 &amp; 966, and L. 173 P. 968 Duane MacNeill Found 1" Pipe and referenced: N75W 34.73 P.P., N05E 14.68 P.P., N80E 23.17 8" Maple.</li> </ul>	
B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:  1997: Found 1" Pipe and three existing witnesses: exis. shiner in P.P. N70W 34.60', exis. shiner in Anchor Pole N10E 14.60', 12" Maple N75E 23.10'. Matching the surveys by Duane MacNeill. Distance to M-1, T27N, R7E is compatible with the James Scott Survey and Duane MacNeill Surveys.  This corner is accepted as a careful and faithful perpetuation of the position of the original corner.	
C. Description of monument for corner and accessories established to perpetuate locating	ng the position of the corner:
1997: Set 1/2" iron rod with 3" dia. alum. cap, stamped to ide	
the existing 1" Pipe, 31 feet East of Power Line.	A STATE OF THE PARTY OF THE PAR
References:	AND TE OF MICHIGAN
Exis. shiner in P.P N70W - 34.60'	A STATE OF THE STA
Exis. shiner in Anchor Pole - N10E - 14.60'	THOMAS L. T.
Set tag #31591 in 12" Maple - N75E - 23.10' Set tag #31591 in 5" Oak - S60E - 25.45'	TAND TAND
Set tag #31391 III 3 Oak - 300E - 23.43	SURVEYOR #
	31591 10 3
	The state of the s
-1 1 · · ·	LAND SURTHER
Signed by Thomas L. Fabis Date Aug	ust 15, 1997