SURVEY & REMONUMENTATION

MAR 0 4 1998

1997 Alcona County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	SE	CT	(\cap)	Ñ١
- .	-	₩ 8		1 ¥
-or corners in	7			

Alcona Located In: Corner Code #

1. Public Land Survey T27N R 7E T27NR 8E

2. Property Controlling in Section 3. Miscellaneous Property in Sec.

APPROVED LAND COTHER PA 345 of 1990

ALCONA COUNTY 130/47

RECORDED

Date 10-31-1997

1 Time 3:30 PM


thee Doris A. Gauthier REGISTER OF DEEDS

Register of Deeds Stamp & File Number

Lot No. , Recorded Plat Private Claims

I, <u>Daniel T. Kibbe</u>, in a field survey on <u>April 1</u>, 19 <u>97</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration: 1838:

GLO Survey by Lewis Clason - set post, referenced: 1914:

GLO Survey by Lewis Clason - set post, referenced: Y. Pine 18 - S 40 W - 29. County Survey by Andrew J. Freer - fd. sleigh rail 38" long, 4" wide, 2" thick with 4 holes

County Survey by Andrew J. Freer - fd. sleigh rail 38" long, 4" wide, ½" thick with 4 holes 1916:

Survey by D.R. MacNeil - fd. P.K. nail, referenced: S 50 W - 78.18' P. Pole / S 50 E 68.12' Fence post / N 30 W - 69.94' Fence Post. 1979:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997: Found P.K. nail over R.R. spike 1' east of N-S centerline, in centerline east and on fence line west.

This corner position is compatible with county & local surveys. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 3" Alcona County cap stamped to identify the corner over 2" iron rod in 1997: monument box.

Referenced:

N30°W - 72.9' - fd. nail in leaning fence post S35°E - 52.55' - fd. tag #15410 in Power Pole S60°E - 68.00' - set nail & tag in fence post N20°W - 89.82' - set nail & tag in gate post S60°W - 76.17' - fd. nail & tag in power pole

Signed by Surveyor's Michigan License No. 37278

Date October 22, 1997

