SURVEY & REMONUMENTATION

MAR 04 1998

CE	CTI	ON

1997 Alcona County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

~ ,	P A 345 of 1990 LCONA COUNTY
Dete	7/30/47
County F	o. Del R. En
	RECORDED
Date /	0-31-1997

APPROVED LAND COENTR

REMON LIBER _ PAGE _27' Just ! 3 of M Doris A. Gauthier REGISTER OF DEEDS


Register of Deeds Stamp & File Number

For corners in Corner Code # Located In: Alcona T27N R 7E 1. Public Land Survey T27N R 8E 2. Property Controlling in Section 3. Miscellaneous Property in Sec.

_,Recorded Plat _ 5. Private Claims

 $\text{I,} \underline{\quad \text{Daniel T. Kibbe}}, \text{ in a field survey on } \underline{\quad \text{April 1.}}, \text{19} \underline{\quad \text{97}} \text{ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in the property of the pr$ conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1838: GLO Survey by Lewis Clason - set post, referenced: Y. Pine 15 - N39W - 56.

1914: County Survey by Andrew J. Freer - set gas pipe 27" long 1½" dia. replacing ½ post, referenced: B. Oak 10 - N 67 E - 17 / Spr. Pine 10 - S 57½ E - 17.5

1977: Survey by D.R. MacNeil - referenced: S 80 E - 27.87 - 10" Oak / S 55 W - 39.19 - 10" Oak / N 50 W - 24 54 - 12" W Pine N 50 W - 34.54 - 12" W. Pine.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
97: Fd. P.K. nail at D.R.M. ½ corner position 3.3' East of centerline. Also fd. boat spike 1.6' North and 0.3' East. Also fd. 3/4" bar 1.3' North and 2.8' West.

This corner position is compatible with county & local surveys. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1997: Placed 3" Alcona County cap stamped to identify the corner over 2" iron rod in monument box.

Referenced:

N60°W - 34.46' - Fd. nail and tag in 16" White Pine S80°E - 27.60' - set nail & tag in 14" Oak S70°W - 32.36' - set nail & tag in 8" Red Pine

N30°E - 57.81' - set nail & tag in 16" Red Pine

Signed by Surveyor's Michigan License No. 37278

1997 Date October 22,

