

*Conservation*

CONS. 4047  
REV. 10/60

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 27 N.R. 8 E


Alcona COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 13 and 24

CORNER MONUMENT Set 1" x 24" pipe, below surface

DATE MONUMENT PLACED AND WITNESSED 10/6/61

WITNESSES TO CORNER.....



7" R. Pine - N20E - 54.7 feet

6" R. Pine - S22E - 50.3 feet

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set while making a survey in section 13.  
Set corner at midpoint on line between section corners. Falls in  
center of E-W road, and nearly in line with old fence south. Could  
find no evidence of any previous corner.

SURVEYOR'S SEAL

SIGNED

*Kenneth J. Ostling*  
REGISTERED LAND SURVEYOR

DATE 10/9/61