DEC 1 6 1996

1996 ALCONA COUNTY REMONUMENTATION CORNER

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Alcona C Remonur	mentation
Liber	Page 197
PEL	(ABACA

	Filing Requirement of Act 74, Mich. P.A. 1970		DECORP.
For corners in	Located In:	Corner Code #	RECORDED
Alcona	_ Located in:	content code #	
Public Land Survey	T _27N R _8E F _27N R _9E T _28N R _8E T _28N R _9E	M-13 PA SON H	Nov 18 8 44 AH '96 Same a la thice
	S T R	40 K11/Q	MESS TO THE COMM
-	S T R		
	S T R	· · · · · · · · · · · · · · · · · · ·	gister of Deeds Stamp & File Number
Property in Section	S T R	A A Course	
A. I. A.M. Branch	and a Dist	٥ ت 🔻	T27N- R8E
4. Lot No, Reco			- A B C D E F G H I J K L
5. Private Claims			- 2 6 - 5 - 4 - 3 - 2 - 1 -
		·	
			4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I, <u>Thomas L. Fabis</u> , in a field survey on <u>November 7</u> , 19 <u>96</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and			5 6 18 -17 -16 -15 -14 -13 - 7 8 -19 -20 -21 -22 -23 -24 -
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a			
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found			10 30 29 28 27 26 25
as expressed below:		·	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded		12 - 31 - 32 - 33 - 34 - 35 - 36 -	
on this certificate.			12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. Survey by Lewis Clason - Set post & referenced: (W. Pine 15 - S85E - 11, 1838: Y. Pine 24 - N59W - 58)

(E. C. Sur.) - referenced: (W. Pine Stump 26 - N13E - 50, Early County Survey: Y. Pine $26 - N4\frac{1}{2}W - 63$)

1985:

Survey (Liber 201 Page 17) by John Oliver - Found P.K. over iron. U.S.D.A. Survey (Liber 227 Pages 798 & 799) by Robert Mitchell - Found P.K. over 1989: 12" Gas Pipe and referenced.

1994: MDOT Survey by Clifford Lindgren - Found 1/2" rod and referenced.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1996: Found 1/2" iron rod in centerline of paved road and 4 existing witnesses.

The position of this corner is compatible with State, Federal, and local surveys and is accepted as a careful and faithful perpetuation of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3" dia. Brass cap, stamped to identify the corner over a 1/2" iron rod inside a monument box which was installed during a recent County Road Construction Project. References:

24" Oak - S20E - 84.45" 10" W. Pine - N84E - 80.05 8" J. Pine - N55W - 72.73" P. Pole - S66W - 52.14[†] (New Wit.) P. Pole - S42E - 43.90'

31591

Surveyor's Michigan License No.

URVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

FABIS

LAND No. 31591