## SURVEY & REMONUMENTATION

FEB 1 9 1999

**SECTION** 

1998 Alcona County Remonumentation Corner LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Alcona County
Remonumentation
Liber 1 Page 312

| For con                 | ners in  |  | •  | Filed for Record in  |
|-------------------------|--|--|--|--|
|                         | Alcona   | Located In:  | Corner Code #  | HECUNA COUNTY MICHIGAN   |
|                         | (County)   |  | Comor Codo n   | On 12-11-1998 Ot 02.21.12  |
| 1. Pub                  | lic Land Survey  | T <u>27N</u> R <u>9E</u><br>TR                                   | F-9  | OR 9.00  |
|                         |  | T R  |  | APPROVED LAND CORNER<br>P A 345 of 1990                                  |
|                         |  | T R  |  | ALCONA COUNTY  |
|                         | perty Controlling  | S T R  |  | Date 9/22/97   |
|                         | ection   | STR  | <del></del>  | County Rep DJR tu  |
|                         | cellaneous<br>perty in Sec.  | S T R<br>S   | <del></del>  | ·  |
| . 101                   | sorry in occ.  | · · · · · · · · · · · · · · · · · · ·                            |  | Register of Deeds Stamp & File Number                                    |
|                         |  |  |  |  |
|                         |  | corded Plat  |  | ABCDEFGHIJK  |
| 5. Priv                 | ate Claims   |  |  | _ 1  |
|                         |  |  |  | 3 3 3  |
|                         |  |  |  | 4 - 7 - 8 - 9 - 10 - 11  |
| I, Danie                | <u>IT, Kibbe</u> , in a field  | d survey on April 8  | , 19 <u>98</u> do hereby state that u  | nder   |
| requirem                | ents of P.A. 74, Michig  | gan P.A. of 1970, the corner poi                                 | nts mentioned in lines 1 and 2 al<br>uired in the current manual of su                     | pove 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1                               |
| instructi               | ons of the United State  | es Department of the Interior, E                                 | dired in the current manual of su<br>Bureau of Land Management or                          | by a 7   |
| decree o                | of a Court of Law and /  | or that the corner points mention                                | ned in lines 3, 4 and 5 above we   | re in 0 19 20 21 22 22   |
|                         |  | the Michigan Board of Land Sui<br>, monumented, recovered, found | veyors or by a Decree of a Coulas expressed below:   | rt of  |
| 3.2                     |  |  | ·  | 10 -30 - 29 - 28 - 27 - 26 - 2   |
| NOTE:                   |  | ers, all in the same town and rar                                | nge, may be recorded   | 11   |
|                         | on this certificate.   |  |  | 12 -31323435   |
|                         |  |  |  | 13   |
| A. De                   | _  | nonument and accessories ar                                      | •  | ·  |
| 1840:<br>1978:<br>1979: | Survey by John F. (<br>Survey by John F. (   | Dliver - Recorded Liber 174 p                                    | post, referenced: Beech 6-S<br>g 245, referenced corner.<br>9, set 1/2" rod & cap, referen |  |
| 1991:                   |  |  | Liber 1 pg 406A, Existing 1/2  | " iron rod in the center of county road, fence                           |
| 1991:                   | south, referenced:<br>Survey by David B.   | Fence post-N50W-64.56'/10  | )" Pine-N05E-49.45'/7" Pine-   | S55E-51.74'/Utility Pole-S40W-62.43'<br>50W-64.56'/10" Pine-N05E-49.45'/ |
| B. De                   | scription of corner e  | vidence found and/or method                                      | applied in restoring or reesta   | ablishing corner:  |
| 1998:                   |  | •  |  | Tree line to S 6' East of fence to N.                                    |
|                         |  | is compatible with county & position of the original corne       |  | osition is accepted as a careful and faithful                            |
| C.                      | Description of mont  | ument for corner and accesse                                     | pries established to perpetuat   | e locating the position of the corner:                                   |
| 1998:                   | Placed 3" Alcona County cap stamped to identify the corner over 1/2" iron rod in monument box. Referenced: |  |  |  |
|                         |  | in utility pole-S36E-74.63'                                      |  |  |
|                         |  | in 7" pine-\$45E-51.75'  |  |  |
|                         |  | in 10" pine-N05E-49,50' in fence post-N50W-64,78'                |  |  |
|                         |  |  |  |  |
|                         |  |  |  |  |
|                         |  |  | Section .  |  |
| -                       |  |  | The said of the  |  |



Signed by rull buth

Surveyor's Michigan License No.

Date <u>December 7, 1998</u>