APR 2 1 1994

## 1993 ALCONA COUNTY REMONUMENTATION CORNER

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Fo	r corners in	Filing Requ	irement of Act 74, Mich. I	P.A. 1970		RE	COR	DED				
<del></del>	Alcona	_ Located In:	Corner Code ##   Remo			on Liber 1 Page 34						
	(County)							_				
1.	Public Land Survey	T <u>27N</u> R <u>9E</u> T R	<u>K - 4</u>	į	JEC	21	4	21 PH	'93			
		T R			1		ri i	g. L		_		
		T R		0	(Ja		,	DEEDS	مسلمل	,		
2.	Property Controlling in Section	S R			Ąţ			, MICHE	ian			
3.	Miscellaneous							<b>.</b>	o e:.		ı	
-	Property in Sec.	S R		Regist	erc	of Dec	eas S	tamp	x File	Numi	Der 	
4.	Lot No , Red	corded Plat		· <del></del>	Δ	вс	D	E F	е н	i J	K I	
5.	Private Claims				<u>.</u> ^	ΪĬ	Ť	<u>-                                    </u>	ĬΪ	ΪĬ	Ť	
				4	}	6	- 5	<b>à</b>	3-	- -2-	1	
				•	<u>`</u>		1			11	$\top$	
	Duane R. MacNeill	in a field curvey on	August 2, 19 93		<u>:</u>	7	- 8	9 	10-	<del>                                     </del>	•	
			A. of 1970, the corner points men	tioned								
		•	and rules therefore as required	in the	Ľ	ויייייייייייייייייייייייייייייייייייי	-17—	16-	15-	14-		
		•	artment of the Interior, Bureau o ner points mentioned in lines 3, 4	Lanu							1	
abo	ove were in conformance with	the rules of the Michigan Board	of Land Surveyors or by a Decr	ee of a		"	-201	21	22-	23		
		established, monumented, re	-monumented, recovered, fou	nd as	$\Gamma$							
	oressed below:	mann all in the come town	and range may be recorded		1	30	-29 	<u>28</u> 	27-	1 26		
NU	TE: Not more than 4 cor on this certificate.	ners, all in the same town	and range, may be recorded	1			32	32	34			
				1:	- [	ïL	Ĭ.		L Ţ	Ĭ		
A.	Description of original me	onument and accessories a	nd/or subsequent restoratio	n:								
	1838 - Set by U.S.	Deputy 197	5 - Found 3"x3" Ceda	ır	1	988	– Ur	reco	rdec	l sur	·ve <sub>3</sub>	
•	Surveyor as		Stake by D.R. Ma					.s. s				
	split of 80.	.00 chains.	in recorded surv	æy.				soc.		ınd 1	1 1,	
							11	ron b	ar.			
	<u>Witnesses:</u>		No Witnesses		Witnesses:							
	Fir 8 N18W 16					65°		6.9	8	Aspe	n	
	Cedar 16 S45E 20	)						4.2 9.3		Aspe		
8.	Description of corner evid	dence found and/or method	dapplied in restoring or rees	tablishing co			<b></b>	7.3	Ü	Cedo	r t	
	1993 - Found 2"x2"	iron stake with cap during remonumentat	#31591, very beat-	ıp (mushro	OM	ed)	witi	n wit	nes	ses a	and	
		rded by T. Fabis P.S tnesses - tagged L.S	5. #31591 found exist 5. #22435.	ting 2"x2'	i	ron	stal	ke wi	th :	3		
	Witnesses:											
	N 40° E 4.22' 8'	Aspen fd.										
	S 10° E 9.32' 6'	'Cedar fd.									,	
	N 80° W 6.92' 7'											
	S 20° W 15.55' 4'	'Cedar set.										
			ron bar in 1988 and witness colaborate :		Γ.	Fabi	s ii	n 199	10 as	s a		
C.	Description of monument	for corner and accessories	s established to perpetuate l	ocating the p	osii	tion a	f the	come	r:			

Alcona County Remonumentation Aluminum Cap, appropriately stamped, secured to  $1/2^n$  re-rod driven next to  $2^n \times 2^n$  iron stake.

## Witnesses:

N 40° W 20.91 5" Cedar S 40° W S 35° E N 55° E 4" Cedar 5" Cedar 15.40 9.24

9" Poplar 4.29

Signed by

Surveyor's Michigan License No. \_

19237

<u>December 16</u>

FORM APPROVED BY MICHIGAN STATE BOARD OF SAID SMITH DORS, MAY 28, BEVISED JAN.

William Control