APR 2 1 1994

1993 ALCONA COUNTY

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Fο	r corners in	i mild treduiter	Hent Of Act 74, Mich. P.A.		
Alcona			4	"RECORDED	
_	(County)	Located In:	Corner Code ##	D 1/1 1 D /0	
			1	Remon Liber 1 Page 48	
1.	Public Land Survey	T 27N R9-10E	<u> </u>	DEC 21 4 23 PM '93	
		T R		OEC C1	
		T R		Sain a Buthier	
		T R		Davie a Bouthier	
2.		T R		REGISTER OF DEEDS ALCONA COUNTY, MICHIGAN	
	in Section S	T R		ALCONA COMPANY	
3.		T R		Register of Deeds Stamp & File Number	
	Property in Sec. S	T R			
	1 - 1 - 1				
	Lot No , Recor			A B C D E F G H I J K L	
Ð.	Private Claims				
				3	
1	Duane R. MacNeill 🔐	a field suggest on Deci	ember 1. 10 93	5 1 3 1 1 1 1 1	
do	do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned				
in i	in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					
	ove were in conformance with the	•		20 20 23 23 23	
	urt of Law; established, re-est				
exp	pressed below:			10 30 29 28 27 26 2	
NC	TE: Not more than 4 corner	rs, all in the same town and	range, may be recorded	11	
	on this certificate.			12 31 32 33 34 35 3	
				13	
Α.	Description of original monu				
	<u>1838</u> - Set by Lewis			corded by Donald Marlatt #18660	
	Surveyor - Ce	dar post.		ınd 1¼" pipe and 3"x3" Sq. Cedar	
	Witnesses:			ake believed established in 1934	
			by	George Henning.	
	Cedar 7 S42½W 22		1000		
	do 6 N12¼W 05		<u>Witnesses</u>) *	
	N.B.T.'s - not dated W. Pine stump 24 N22E 69		N 65° W	9.05' Pine stump	
			N 45° W 2	23.5' 10" Cedar	
		565%W 85			
8.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
	No evidence of origi	inal corner or acces	sories found after a	thorough search.	
	1993 - Remonumentati	ion crew found 1½" p	ipe and 6" square moi	nument with no re-rod or iron	
	in same. The	e crew drove a 1/2"	re-rod into the 1½"	oipe.	

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Alcona County Remonumentation Aluminum Cap, secured to 1/2" re-rod driven into $1 \xi^\mu$ pipe, appropriately stamped.

Witnesses:

Signed by

11.23 10" Cedar N 50° E 12" Cedar N 30° W 28.08

8" Cedar S 45° W 10.16

S 45° E 6" Cedar 6.21

Witnesses were duplex nails bearing a brass washer stamped license #19237.

Date December 16.

Surveyor's Michigan License No. 19237

Cember 16, 1993

