1993 Alcona County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE

| Alcona Col Remonum Liber/ | | 12 |
|---------------------------------|------|----|
| "RECO | RNFN | |

| For | r corners in | Filing Requi | rement of Act 74, Mich. P.A | 1970 "R | ECORNEN | | |
|--|---|--|--|---|--|-----------|--|
| Al | Cona (County) | Located In: | Corner Code ## | | Page 12 | | |
| 1. | Public Land Survey | T _28N R _ 7E T R T R T R | M=6 | Sanie | 1 17 PN '93 | | |
| 2. | Property Controlling in Section | S T R S T R | | . RE | REGISTER OF DELOS ALCONA CORPUTY, MICHIGAN | | |
| 3. | Miscellaneous Property in Sec. | S T R S T R | | Register of Deeds | s Stamp & File Numb | er | |
| 4. 5. | Lot No, Private Claims | Recorded Plat | | A B C | D E F G H I J P | K L | |
| | , | | | 3 - 5 - 5 | 4 3 2 - | | |
| do fin li curi Mar abo Cou exp | nereby certify that under reines 1 and 2 above were rent manual of survey instagement or by a decree over were in conformance wirt of Law; established, ressed below: | Lein a field survey on <u>Sept</u> . equirements of P.A. 74, Michigan P.A. in conformance with regulations all ructions of the United States Depa f a Court of Law and/or that the corn vith the rules of the Michigan Board re-established, monumented, re- | of 1970, the corner points mention not rules therefore as required in t rtment of the Interior, Bureau of La er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found | ned 6 18 17 17 18 18 18 18 18 18 18 18 18 18 18 18 18 | 7 - 18 - 15 - 14 - 14 - 14 - 14 - 14 - 14 - 14 | 13-24-25- | |
| NO. | TE: Not more than 4 on this certificate | corners, all in the same town a b. | nd range, may be recorded | 12 31 32 | 33 34 35 | 36- | |

A. Description of original monument and accessories and/or subsequent restoration:

1839: G.L.O. Survey by Lewis Clason - Set post and referenced W. Birch 6 - S8°W - 25 / Aspen 10 - N22°W - 23

1962: Survey by James L. Scott for Plat of Tollson Subdivision

1981: Survey by David B. Guthrie - Found 1" Iron Pipe and Referenced

1993: Survey by David B. Guthrie - Found 1" Iron Pipe, verified previous references.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found 1" Iron Pipe

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: Set 1/2" X 24" Iron Rod with a 3" brass cap Stamped to identify the corner. Referenced -

N31°E - Utility Pole - 74.18 Feet N53°E - Twin 6" Ash - 42.00 Feet S70°E - 6" Aspen - 33.60 Feet S39°E - 7" Aspen - 83.00 Feet

| | DIB. | tithe |
|-----------|------|-------|
| Signed by | 1/4 | una |