## SURVEY & REMONUMENTATION

1994 Alcona County Remonumentation Corner APR 25 1995 LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 For corners in

Alcona Remon	County umentation	
Liber	1 Page 75	
	RECORDED	

Alcona Located In: Corner Code ## DEC 9 10 33 AN 194 1. Public Land Survey T <u>28N R 8E</u> \_\_\_ R \_\_ 2. Property Controlling ALCONA COUNTY ARCHIGAN S \_\_\_\_ R \_ in Section E.T.L. 3. Miscelianeous Register of Deeds Stamp & File Number Property in Sec.

I, David B. Guthrie in a field survey on June 6 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

11 12

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. Survey by Lewis Clason - Set post and referenced Beech 6 - S50W - 04 / Hrd. Maple - N27½W - 24 1839:

1907: Survey by Edw. Chapelle - Light Gray Boulder

1971: Survey by Donald E. Marlatt

1973:

\_\_\_\_, Recorded Plat \_\_

5. Private Claims \_\_\_

Survey by James L. Scott Survey by D.R. MacNeill and Associates - Found P.K. Nail 1977:

1979: Survey by David B. Guthrie - Found Nail

1982: Survey by D.R. MacNeill and Associates - Found P.K. Nail

1983: Survey by David B. Guthrie - Found Nail

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found P.K. Nail

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced with a 5/8" Iron Rod with a 3" Brass Cap stamped to identify the corner placed in a Monument Box. OF MICH

\_\_\_\_\_ Date \_\_\_

Referenced -

S35°W - Utility Pole - 55.15 feet S40°W - R.O.W. Marker - 56.55 feet S04°W - 7" Maple - 59.81 feet S33°E - 8" Pine - 56.76 feet

B. Lile

Surveyor's Michigan License No. \_