MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_28 NR9_E___

					- -	▼Tōone	<u></u> .		_ COUNT	⁻ Y
DESCRIPTION	OF	CORNER	<u>OTO</u>	ing co	rner c	common to	Secti R9E	ons 4	\$_5_ on	
DESCRIPTION	OF	CORNER	MONU	MENT_	i pi	pe with	4" bra	ēs cal	P	
WITTNESSES	то	CORNER								
			5*	Cedar	_	South	-	31/2	links	
			g#	Cedar	-	855W	-	58	links	
				·						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a survey in this area. Corner was set in relation to corner for Sections 32 and 33, T29N R9E as per government record. Found no corner in place.

Corner common to Sections 32 & 33, T29N RyE is 29 links west.

Corner was placed and witnessed April 12, 1957.

SURVEYORS SEAL

SIGNED Silly & Buelles DATE 5/9/57