

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 28. NR. 9. E. . .

Alcona

COUNTY

DESCRIPTION OF CORNER East 1/8 corner between Sections 4 & 9 . . .

DESCRIPTION OF CORNER MONUMENT 1" x 24" pipe . . .

WITNESSES TO CORNER . . .

7" Cedar	-	N41E	-	53 links
5" Cedar	-	N57W	-	60 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement by Forestry Division survey crew while making a survey in this area.

Corner was placed and witnessed April 11, 1957.

SURVEYORS SEAL

SIGNED

*Billy D. Buchler*  
REGISTERED LAND SURVEYOR

DATE 5/9/57