

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 N.R. 9 E

need folder + county


Alcona COUNTY

DESCRIPTION OF CORNER 1/4 corner common to sections 10 - 11

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-13-66

WITNESSES TO CORNER.....



6" W. Birch S 13 E 31.1'

7" S. Maple N 45 W 24.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey of Section 11. Found 1 1/4" pipe in place as established in a previous survey by unknown. Falls at midpoint and very nearly on line between section corners. Nothing left for USBTs.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Bellamy* DATE Nov. 18, 1966
REGISTERED LAND SURVEYOR #10068