

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Alger
(County)

	Located In:	Corner Code \neq
1. Public Land Survey	T <u>44N</u> R <u>21W</u>	<u>J3</u>
	T _____ R _____	<u>J1</u>
	T _____ R _____	<u>J3</u>
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Keith Sackett, in a field survey on May 15, 1991, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

<u>J3</u>	<u>J1</u>	<u>J3</u>
Quarter corner common to Sections 3 and 10. Original monument and accessories not found.	Original monument and accessories not found.	Quarter corner common to Sections 2 and 11. Original monument and accessories not found. Found old fence iron S57E 48.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

<u>J3</u>	<u>J1</u>	<u>J3</u>
Restored midway and on line.	Restored midway and on line.	Restored midway and on line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>J3</u>	<u>J1</u>	<u>J3</u>
DNR monument. 7" sugar maple N52E 20.85' NBT 10" cedar S36E 14.9' NBT 7" sugar maple S31W 11.6' NBT 9" sugar maple N48W 29.9' NBT	DNR Wood post North 1.0' 8" black cherry S51E 14.1' NBT 6" sugar maple S03E 21.75' NBT 10" white spruce N81W 22.6' NBT	DNR 15" sugar maple N80E 12.0' NBT 12" basswood S47E 7.6' NBT 3" ironwood S26W 8.0' NBT 8" sugar maple N09W 18.3' NBT

Signed by Keith Sackett Date _____
 Surveyor's Michigan License No. _____ 19006

